

Part 573 Safety Recall Report

18V-217

Manufacturer Name : Keystone RV Company**Submission Date :** APR 05, 2018**NHTSA Recall No. :** 18V-217**Manufacturer Recall No. :** 18-316**Manufacturer Information :**

Manufacturer Name : Keystone RV Company

Address : PO Box 2000
2642 Hackberry Drive Goshen IN
46527

Company phone : 574-535-2100

Population :

Number of potentially involved : 876

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2018-2018 Crossroads Cruiser 25RL, 28RD, 28RL, 29BH, 29RK, 29SI, 30MD

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : All fifth wheel models affected

Production Dates : SEP 07, 2017 - MAR 01, 2018

VIN Range 1 : Begin : 4YDF29S23J6320352 End : 4YDF29S20J6320356 Not sequentialVIN Range 2 : Begin : 4YDF30M23J6320390 End : 4YDF30M23J6320728 Not sequentialVehicle 2 : 2018-2018 Crossroads Volante 22RB, 240RL, 250RL, 25BH, 270BH, 280RL, 28BH,
28RL, 290RL, 295BH, 30EK, 310BH, 31BH, 32FB, 32SB, 33BR, 33DB, 360DB, 365MD

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : All fifth wheel and travel trailer models affected

Production Dates : SEP 08, 2017 - FEB 05, 2018

VIN Range 1 : Begin : 4YDF31023J6360657 End : 4YDT22R26J6361459 Not sequential**Description of Defect :**

Description of the Defect : It has been decided that the vehicles in the recall population may have a brake wire that is improperly attached to the spring assembly on the axles.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Under certain conditions during travel, if the brake wire shorts, there is an increased risk of damage or fire to the unit.

Description of the Cause : Production attached the brake wire to the axle springs using a zip tie fastener.
Identification of Any Warning that can Occur : Loss of braking ability, an error message on the customers brake controller, or visible damage to the wiring.

Supplier Identification :

Component Manufacturer

Name : NR
Address : NR
NR
Country : NR

Chronology :

3/15/2018 – Report was made by a transport driver that the brakes were not working. Upon inspection it was found that the wiring was damaged by the axle springs.
3/15/2018 – Investigation opened. All affected units were put on hold and the brake wiring was inspected and repaired as needed.
4/2/2018 – Investigation concluded and scope completed.

Description of Remedy :

Description of Remedy Program : The remedy is to remove the zip tie attaching the wires to the axle springs and relocate the wiring as needed.
How Remedy Component Differs from Recalled Component : NA
Identify How/When Recall Condition was Corrected in Production : Units were quarantined, inspected then repaired as indicated by inspection

Recall Schedule :

Description of Recall Schedule : Keystone will notify the dealers and owners of the recreational vehicles by letter. A final copy of the owner letter will be provided to NHTSA, along with the dealer repair procedures.
Planned Dealer Notification Date : JUN 04, 2018 - JUN 04, 2018
Planned Owner Notification Date : JUN 04, 2018 - JUN 04, 2018

* NR - Not Reported