

Part 573 Safety Recall Report

18V-505

Manufacturer Name : Newmar Corporation**Submission Date :** AUG 02, 2018**NHTSA Recall No. :** 18V-505**Manufacturer Recall No. :** 18V-353**Manufacturer Information :**

Manufacturer Name : Newmar Corporation

Address : 355 North Delaware Street

PO Box 30 Nappanee IN 46550

Company phone : 574-773-7791

Population :

Number of potentially involved : 119

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2017-2019 Newmar Ventana LE

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, insufficiently torqued caliper mounting bolts may not provide adequate clamping force between the brake caliper and the brake anchor plate, potentially resulting in reduced brake effectiveness, which could increase the risk of a vehicle crash and/or property damage. Correction: an authorized DTNA service center will inspect the caliper mounting bolts and torque as needed.

Production Dates : MAR 10, 2017 - JAN 31, 2018

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Vehicle 2 : 2017-2019 Newmar Ventana

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, insufficiently torqued caliper mounting bolts may not provide adequate clamping force between the brake caliper and the brake anchor plate, potentially resulting in reduced brake effectiveness, which could increase the risk of a vehicle crash and/or property damage. Correction: an authorized DTNA service center will inspect the caliper mounting bolts and torque as needed.

Production Dates : MAR 10, 2017 - JAN 31, 2018

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Vehicle 3 : 2018-2018 Newmar Mountain Aire

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, insufficiently torqued caliper mounting bolts may not

Descriptive Information : provide adequate clamping force between the brake caliper and the brake anchor plate, potentially resulting in reduced brake effectiveness, which could increase the risk of a vehicle crash and/or property damage. Correction: an authorized DTNA service center will inspect the caliper mounting bolts and torque as needed.

Production Dates : MAR 10, 2017 - JAN 31, 2018

VIN Range 1 : Begin : NR **End :** NR

Not sequential

Vehicle 4 : 2017-2018 Newmar London Aire

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, insufficiently torqued caliper mounting bolts may not provide adequate clamping force between the brake caliper and the brake anchor plate, potentially resulting in reduced brake effectiveness, which could increase the risk of a vehicle crash and/or property damage. Correction: an authorized DTNA service center will inspect the caliper mounting bolts and torque as needed.

Production Dates : MAR 10, 2017 - JAN 31, 2018

VIN Range 1 : Begin : NR **End :** NR

Not sequential

Vehicle 5 : 2018-2018 Newmar Essex

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, insufficiently torqued caliper mounting bolts may not provide adequate clamping force between the brake caliper and the brake anchor plate, potentially resulting in reduced brake effectiveness, which could increase the risk of a vehicle crash and/or property damage. Correction: an authorized DTNA service center will inspect the caliper mounting bolts and torque as needed.

Production Dates : MAR 10, 2017 - JAN 31, 2018

VIN Range 1 : Begin : NR **End :** NR

Not sequential

Description of Defect :

Description of the Defect : On certain motorhomes, insufficiently torqued caliper mounting bolts may not provide adequate clamping force between the brake caliper and the brake anchor plate, potentially resulting in reduced brake effectiveness, which could increase the risk of a vehicle crash and/or property damage. Correction: an authorized DTNA service center will inspect the caliper mounting bolts and torque as needed.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : insufficiently torqued caliper mounting bolts may not provide adequate clamping force between the brake caliper and the brake anchor plate,

potentially resulting in reduced brake effectiveness, which could increase the risk of a vehicle crash and/or property damage.

Description of the Cause : insufficiently torqued caliper mounting bolts may not provide adequate clamping force between the brake caliper and the brake anchor plate

Identification of Any Warning that can Occur : NR

Supplier Identification :

Component Manufacturer

Name : Daimler Trucks North America LLC
Address : P.O. Box 3849
Portland OREGON 97208
Country : United States

Chronology :

On 8/1/2018 Newmar was given notice of defect by Daimler Trucks North America LLC. On 8/2/2018, Newmar is giving notice of defect to NHTSA on Newmar motorhomes.

Description of Remedy :

Description of Remedy Program : an authorized DTNA service center will inspect the caliper mounting bolts and torque as needed at no cost to the customer.

How Remedy Component Differs from Recalled Component : The caliper mounting bolts will be torqued correctly.

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : On or before 10/01/2018, customer/dealer letters will be sent out.
Planned Dealer Notification Date : OCT 01, 2018 - OCT 01, 2018
Planned Owner Notification Date : OCT 01, 2018 - OCT 01, 2018

* NR - Not Reported