

# Part 573 Safety Recall Report

# 18V-792

**Manufacturer Name :** Altec Industries Inc.

**Submission Date :** NOV 09, 2018

**NHTSA Recall No. :** 18V-792

**Manufacturer Recall No. :** CSN 704



## Manufacturer Information :

**Manufacturer Name :** Altec Industries Inc.

**Address :** 210 Inverness Center Drive  
Birmingham AL 35242

**Company phone :** 205-991-7733

## Population :

**Number of potentially involved :** 186

**Estimated percentage with defect :** 100 %

## Vehicle Information :

**Vehicle 1 :** 2017-2018 Altec AT37-G, AT40, AT37/41/48, L37M Aerial Devices

**Vehicle Type :**

**Body Style :**

**Power Train :** NR

**Descriptive Information :** The recall population was determined by a review of production records to determine units built with a specific fuse bracket.

**Production Dates :** JUN 30, 2017 - JUN 29, 2018

**VIN Range 1 : Begin :**

NR

**End :** NR

Not sequential

## Description of Defect :

**Description of the Defect :** Wiring exposed to abrasion

**FMVSS 1 :** NR

**FMVSS 2 :** NR

**Description of the Safety Risk :** Wiring exposed to abrasion can result in a thermal event which can increase the risk of personal injury and/or property damage

**Description of the Cause :** NR

**Identification of Any Warning that can Occur :** Operator and preventive maintenance inspections may detect abrasion to wiring insulation and evidence of shorting or arcing

## Supplier Identification :

### Component Manufacturer

**Name :** NR

**Address :** NR

Country : NR

### Chronology :

In October, a customer reported some issues with under hood wire routing and inconsistencies between units. Altec investigated the issue and determined that some wires were not covered with protective loom and potentially ran over sharp edges.  
There have been no reported incidents

### Description of Remedy :

Description of Remedy Program :	Altec will issue CSN 704 to owners of the affected units requiring to 1) inspect the wiring, 2) replace any damaged protective loom and, 3) install edge guard to the bracket area.
How Remedy Component Differs from Recalled Component :	Edge guard was added to prevent the loom on the inverter wire from rubbing metal on the bracket
Identify How/When Recall Condition was Corrected in Production :	Edge guard was added to prevent the loom on the inverter wire from rubbing metal on the bracket

### Recall Schedule :

Description of Recall Schedule :	Altec will issue CSN 704 to owners of the affected units requiring to 1) inspect the wiring, 2) replace any damaged protective loom and, 3) install edge guard to the bracket area.
Planned Dealer Notification Date :	JAN 07, 2019 - JAN 08, 2019
Planned Owner Notification Date :	JAN 07, 2019 - JAN 08, 2019

\* NR - Not Reported