

Part 573 Safety Recall Report

18V-859

Manufacturer Name : Newmar Corporation**Submission Date :** DEC 04, 2018**NHTSA Recall No. :** 18V-859**Manufacturer Recall No. :** 18V-703**Manufacturer Information :**

Manufacturer Name : Newmar Corporation

Address : 355 North Delaware Street

PO Box 30 Nappanee IN 46550

Company phone : 574-773-7791

Population :

Number of potentially involved : 308

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2018-2019 Newmar Essex

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, the brake caliper mounting bolts may be incorrectly torqued. Insufficiently torqued bolts may not provide adequate clamping force between the brake caliper and brake anchor plate potentially resulting in reduced brake effectiveness. Reduced brake effectiveness could lead to a vehicle crash and/or property damage. Correction: Daimler Trucks North America LLC service facilities will inspect and repair as necessary. Essex model total is 8 motor homes.

Production Dates : NOV 10, 2017 - OCT 31, 2018

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Vehicle 2 : 2018-2019 Newmar Ventana LE

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, the brake caliper mounting bolts may be incorrectly torqued. Insufficiently torqued bolts may not provide adequate clamping force between the brake caliper and brake anchor plate potentially resulting in reduced brake effectiveness. Reduced brake effectiveness could lead to a vehicle crash and/or property damage. Correction: Daimler Trucks North America LLC service facilities will inspect and repair as necessary. Ventana LE model totals 88 motor homes.

Production Dates : NOV 10, 2017 - OCT 31, 2018

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Vehicle 3 : 2018-2019 Newmar Ventana

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, the brake caliper mounting bolts may be incorrectly torqued. Insufficiently torqued bolts may not provide adequate clamping force between the brake caliper and brake anchor plate potentially resulting in reduced brake effectiveness. Reduced brake effectiveness could lead to a vehicle crash and/or property damage. Correction: Daimler Trucks North America LLC service facilities will inspect and repair as necessary.
Ventana model totals 200 motor homes.

Production Dates : NOV 10, 2017 - OCT 31, 2018

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 4 : 2018-2019 Newmar London Aire

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, the brake caliper mounting bolts may be incorrectly torqued. Insufficiently torqued bolts may not provide adequate clamping force between the brake caliper and brake anchor plate potentially resulting in reduced brake effectiveness. Reduced brake effectiveness could lead to a vehicle crash and/or property damage. Correction: Daimler Trucks North America LLC service facilities will inspect and repair as necessary.
London Aire model totals 8 motor homes.

Production Dates : NOV 10, 2017 - OCT 31, 2018

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 5 : 2018-2019 Newmar Mountain Aire

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, the brake caliper mounting bolts may be incorrectly torqued. Insufficiently torqued bolts may not provide adequate clamping force between the brake caliper and brake anchor plate potentially resulting in reduced brake effectiveness. Reduced brake effectiveness could lead to a vehicle crash and/or property damage. Correction: Daimler Trucks North America LLC service facilities will inspect and repair as necessary.
Mountain Aire model totals 4 motor homes.

Production Dates : NOV 10, 2017 - OCT 31, 2018

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Description of Defect :

Description of the Defect : On certain motorhomes, the brake caliper mounting bolts may be incorrectly torqued. Insufficiently torqued bolts may not provide adequate clamping force between the brake caliper and brake anchor plate potentially resulting in reduced brake effectiveness.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Reduced brake effectiveness could lead to a vehicle crash and/or property damage.

Description of the Cause : The brake caliper mounting bolts may be incorrectly torqued.

Identification of Any Warning that can Occur : NR

Supplier Identification :

Component Manufacturer

Name : Daimler Trucks North America LLC

Address : P.O. Box 4090
Portland OREGON 97208-4090

Country : United States

Chronology :

On 12/3/2018 Newmar was made aware of a safety defect. Today, 12/4/2018 Newmar is giving notice of defect to NHTSA.

Description of Remedy :

Description of Remedy Program : Potentially affected vehicles will be inspected and repaired as necessary at no cost to the customer. Daimler Trucks North America LLC will be conducting this recall in its entirety.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : Customer/Dealer letters will be mailed out on or before 2/2/2019.

Planned Dealer Notification Date : FEB 02, 2019 - FEB 02, 2019

Planned Owner Notification Date : FEB 02, 2019 - FEB 02, 2019

* NR - Not Reported