

Part 573 Safety Recall Report

18V-078

Manufacturer Name : Jayco, Inc.**Submission Date :** JAN 30, 2018**NHTSA Recall No. :** 18V-078**Manufacturer Recall No. :** na**Manufacturer Information :**

Manufacturer Name : Jayco, Inc.

Address : 903 South Main Street

PO Box 460 Middlebury IN 46540

Company phone : 800-283-8267

Population :

Number of potentially involved : 17

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2017-2017 Jayco Class A motorhome Precept

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : H1UL0269-0274+ 0304

H1UT0128-0134, 0136-0139

Population determined by matching Precept unit serial # to Ford chassis listing

Production Dates : DEC 12, 2016 - FEB 22, 2017

VIN Range 1 : Begin :

NR

End : NR

 Not sequential**Description of Defect :**

Description of the Defect : Per Ford Recall 17V768 - Chassis equipped with an antilock Brake system (ABS) may have a brake hydraulic Electronic Control Unit (HECU) that is missing valve block ball plugs.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Per Ford - HECU may lead brake fluid or ingest air during Electronic Brake Distribution and/or ABS activation. These conditions may increase the risk of a crash.

Air ingestion may result in unexpected, increased brake pedal travel.

The amount of brake fluid that leaks is dependent on the number and duration of WEBD and ABS events that occur. Sufficient loss of brake fluid may result in increased pedal travel and/or increased stopping distance. The brake warning light may illuminate as a result.

Description of the Cause : NR

Identification of Any Warning
that can Occur :

Supplier Identification :

Component Manufacturer

Name : NR
Address : NR
NR
Country : NR

Chronology :

12-20-2017 received email from Ford of Canada regarding FORD recall 17S41 - affected chassis listing was provided. 1-2018 scope created of affected Jayco Motorized Product - 1-25-18 Jayco Corp. Safety Steering Committee reviewed details and decided that a recall should be filed for the Jayco motorized product affected by the FORD recall. .

Description of Remedy :

Description of Remedy Program : FORD service center will inspect the hydraulic block and replace the HECU if the ball plugs are not present at no cost to current owner on record.

How Remedy Component Differs NR
from Recalled Component :

Identify How/When Recall Condition NR
was Corrected in Production :

Recall Schedule :

Description of Recall Schedule : Entegra will release recall notification letter to current owner on record under Entegra recall number assigned by NHTSA. Notification letter will provide Ford contact information how to schedule recall remedy at Ford Service Center.

Planned Dealer Notification Date : MAR 30, 2018 - MAR 30, 2018
Planned Owner Notification Date : MAR 30, 2018 - MAR 30, 2018

* NR - Not Reported