

Part 573 Safety Recall Report

18V-144

Manufacturer Name : Newmar Corporation

Submission Date : MAR 02, 2018

NHTSA Recall No. : 18V-144

Manufacturer Recall No. : NR



Manufacturer Information :

Population :

Manufacturer Name : Newmar Corporation

Number of potentially involved : 33

Address : 355 North Delaware Street

Estimated percentage with defect : 100 %

PO Box 30 Nappanee IN 46550

Company phone : 574-773-7791

Vehicle Information :

Vehicle 1 : 2018-2018 Newmar Essex

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, the taillights may become loose and could separate from the vehicle. If the taillights were separate, it could result in following road users being unaware of the driver's intentions, which could increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will secure the taillights using the correct anchorage hardware.

Production Dates : FEB 06, 2017 - JAN 29, 2018

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Description of Defect :

Description of the Defect : On certain motorhomes, the taillights may become loose and could separate from the vehicle. If the taillights were separate, it could result in following road users being unaware of the driver's intentions, which could increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will secure the taillights using the correct anchorage hardware.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : If the vehicle taillights were to separate, it could result in following road users being unaware of the driver's intentions, which could increase the risk of a crash causing injury and/or damage to property.

Description of the Cause : NR

Identification of Any Warning that can Occur : None

Supplier Identification :**Component Manufacturer**

Name : Newmar Corporation
Address : 355 N Delaware St.
Nappanee INDIANA 46550
Country : United States

Chronology :

On 2/23/2018, Newmar was made aware of a potential defect. On 3/2/2018, Newmar is giving notice of a defect.

Description of Remedy :

Description of Remedy Program : Dealers will secure the taillights using the correct anchorage hardware at no cost to the customer.

How Remedy Component Differs from Recalled Component : Longer self tapping screws will be used to secure the same taillight.

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : Newmar letters will be mailed to customer/dealers on or before 05/01/2018.

Planned Dealer Notification Date : MAY 01, 2018 - MAY 01, 2018

Planned Owner Notification Date : MAY 01, 2018 - MAY 01, 2018

* NR - Not Reported