

# Part 573 Safety Recall Report

# 18V-274

**Manufacturer Name :** Winnebago Industries, Inc**Submission Date :** MAY 02, 2018**NHTSA Recall No. :** 18V-274**Manufacturer Recall No. :** 150**Manufacturer Information :**

Manufacturer Name : Winnebago Industries, Inc

Address : PO BOX 152  
605 W. Crystal Lake Rd. Forest City IA  
50436

Company phone : 1-641-585-3535

**Population :**

Number of potentially involved : 293

Estimated percentage with defect : 100 %

**Vehicle Information :**

Vehicle 1 : 2018-2018 Winnebago Travato

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : Population determined using production records. The recalled roof rack was attached with rivets -vs- screws.

Production Dates : MAR 23, 2018 - APR 24, 2018

VIN Range 1 : Begin : NR End : NR  Not sequential

Vehicle 2 : 2018-2019 Winnebago Era

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : Population was determined using production records. The roof rack was attached with the wrong fastners

Production Dates : AUG 09, 2017 - APR 11, 2018

VIN Range 1 : Begin : NR End : NR  Not sequential

Vehicle 3 : 2018-2019 Revel Winnebago

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : Population was determined thru production records

Production Dates : AUG 29, 2017 - APR 16, 2018

VIN Range 1 : Begin : NR End : NR  Not sequential

**Description of Defect :**

Description of the Defect : roof rack can detach from vehicle while going down the road

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : The roof rack could detach while going down the road hitting a vehicle or the road in the path of a oncoming vehicle.

Description of the Cause : The wrong fastener was used to attach the roof rack rail

Identification of Any Warning NR  
that can Occur :

**Supplier Identification :****Component Manufacturer**

Name : NR

Address : NR

NR

Country : NR

**Chronology :**

4-18-18 Dealer notified us he had a unit come in that the " roof rack flew off in transit "

4-19-18 Rework Campaign 688 was issued

4-25-18 Test Report released on strength of fastners used to attach Summit Roof Rack

4-25-18 Safety Committee meeting

4-29-18 Submit to NHTSA recall portal.

**Description of Remedy :**

Description of Remedy Program : Add a screw adjacent to each rivet.

How Remedy Component Differs from Recalled Component : The bracket with have a total of four fasteners -vs- two .

Identify How/When Recall Condition was Corrected in Production : The correct rivets will be used and a screw is being added between the two rivets.

**Recall Schedule :**

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

\* NR - Not Reported