

Part 573 Safety Recall Report

18V-326

Manufacturer Name : Rebel West Powersports LLC**Submission Date :** MAY 17, 2018**NHTSA Recall No. :** 18V-326**Manufacturer Recall No. :** recall1**Manufacturer Information :**

Manufacturer Name : Rebel West Powersports LLC

Address : 75 W Baseline RD

Suite 56 Gilbert AZ 85233

Company phone : 6028425100

Population :

Number of potentially involved : 1

Estimated percentage with defect : NR

Vehicle Information :

Vehicle 1 : 2018-2018 REBEL WEST POWERSPORTS REBEL R4 LSV

Vehicle Type : LOW VOLUME VEHICLES

Body Style : 4-DOOR

Power Train : GAS

Descriptive Information : The recall was determined by a laboratory test. The unit recalled was due to an error by a third party after the vehicle left our facility. The third party changed the rear fenders due to damage that occurred during the loading process and neglected to install the reflectors on the vehicle after they replaced the fenders.

Production Dates : JAN 02, 2018 - MAY 09, 2018

VIN Range 1 : Begin : 1r9ac1342jm830005 End : 1R9AC1342JM830005 Not sequential**Description of Noncompliance :**

Description of the Noncompliance : Rear side reflex reflectors were not present at the time of testing.

FMVSS 1 : 108 - Lamps, reflective devices, and assoc. Equipment

FMVSS 2 : NR

Description of the Safety Risk : Reduces the visibility of the vehicle**Description of the Cause :** NR

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : Rebel West Powersports LLC
Address : 75 W Baseline Rd
Suite 56 Gilbert ARIZONA 85233
Country : United States

Chronology :

We were made aware on 4/30/2018 that our vehicle was tested by the Transportation Research Center, Inc and they found missing rear side reflex reflectors.

Description of Remedy :

Description of Remedy Program : The Non- Compliance of the vehicle was a result of damage to the vehicle after it was released from our facility. The rear fenders were replaced by a third party and not our company.

How Remedy Component Differs from Recalled Component : N/A

Identify How/When Recall Condition was Corrected in Production : As stated above this non- compliance occurred after the vehicle was released to a third party. The vehicle was released to the third party with the required reflex reflectors.

Recall Schedule :

Description of Recall Schedule : We contacted our dealer base and explained the issue and expressed to the dealers need to ensure the reflex reflectors are left on every vehicle.

Planned Dealer Notification Date : MAY 17, 2018 - JUN 17, 2018

Planned Owner Notification Date : MAY 17, 2018 - JUN 17, 2018

* NR - Not Reported