

Part 573 Safety Recall Report

18V-367

Manufacturer Name : MORryde International, Inc.**Submission Date :** JUN 01, 2018**NHTSA Recall No. :** 18V-367**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : MORryde International, Inc.

Address : 1966 Sterling Avenue

Elkhart IN 46516

Company phone : (574) 293-1581

Population :

Number of potentially involved : 904

Estimated percentage with defect : NR

Vehicle Information :

Vehicle 1 : 2018-2018 Ford E-450

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : Audits were completed on March 6, 2018 and u-bolts were torqued correctly. A subsequent audit was performed on April 18, 2018 and found that the u-bolts were not torqued to 170 ft-lb as per specifications. We've identified the lines that were non-compliant and all units that had wheelbase modifications during the time period on the non-compliant lines are recalled.

Production Dates : MAR 06, 2018 - APR 18, 2018

VIN Range 1 : Begin :

NR

End : NR

 Not sequential**Description of Defect :****Description of the Defect :** The u-bolt torque is unverified and may not be tightened to 170 ft-lb.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Insufficient torque on the u-bolts may cause the u-bolts to loosen or break resulting in the potential for the rear axle to break away from the chassis.**Description of the Cause :** NR**Identification of Any Warning that can Occur :** NR**Supplier Identification :**

Component Manufacturer

Name : NR
Address : NR
NR
Country : NR

Chronology :

NR

Description of Remedy :

Description of Remedy Program : NR
How Remedy Component Differs NR
from Recalled Component :
Identify How/When Recall Condition NR
was Corrected in Production :

Recall Schedule :

Description of Recall Schedule : NR
Planned Dealer Notification Date : NR - NR
Planned Owner Notification Date : NR - NR

* NR - Not Reported