

Part 573 Safety Recall Report**18V-547****Manufacturer Name :** Winnebago Industries, Inc**Submission Date :** AUG 17, 2018**NHTSA Recall No. :** 18V-547**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Winnebago Industries, Inc

Address : PO BOX 152
605 W. Crystal Lake Rd. Forest City IA
50436

Company phone : 1-641-585-3535

Population :

Number of potentially involved : 1,066

Estimated percentage with defect : NR

Vehicle Information :

Vehicle 1 : 2018-2019 Winnebago Intent

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : All Winnebago Intent Motorhomes are affected. Other products do not have a mirror in this location.

Production Dates : MAY 08, 2017 - AUG 02, 2018

VIN Range 1 : Begin : NR End : NR

 Not sequential**Description of Defect :**

Description of the Defect : The cabinet mirror over the driver seat may not be mechanically secure, and could come loose.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Increased risk of crash if the mirror detaches while the vehicle is in motion.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : NR

Address : NR
NR
Country : NR

Chronology :

Winnebago Service raised concern of this defect after a mirror came loose and fell into the driver seat. An investigation was started on 08/01/2018 which verified the attachment method was insufficient. On 08/02/2018 a rework campaign was issued to stop shipment of future units and begin rework. On 08/08/2018, a meeting of the Safety Committee was held and the determination was made to conduct a recall campaign.

Description of Remedy :

Description of Remedy Program : Dealer will install 4 screws through the mirror frame, attaching the mirror and frame to the overhead cabinet. The screws will be covered with matching wood plugs. Winnebago authorized service center will submit a Warranty Service Claim to Winnebago.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : Four screws were added for installation of the mirror assembly, fastening to the overhead cabinet.

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported