

Part 573 Safety Recall Report

18V-564

Manufacturer Name : Jayco, Inc.**Submission Date :** AUG 27, 2018**NHTSA Recall No. :** 18V-564**Manufacturer Recall No. :** na**Manufacturer Information :**

Manufacturer Name : Jayco, Inc.

Address : 903 South Main Street

PO Box 460 Middlebury IN 46540

Company phone : 800-283-8267

Population :

Number of potentially involved : 170

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2015-2017 Class C Motorhome Redhawk

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : GM - provided VIN numbers of affected chassis under their recall that were delivered to Jayco - The Chassis VINS were matched to Unit serial numbers of product manufactured on the recalled chassis. Affected Redhawk Class C motorhomes: 2015 F1X10052-0055 X20052-0055

2016 G1X10051-0089 X20051-0063 2017 H1X10051-0140 X20052-0068

Production Dates : FEB 20, 2015 - NOV 28, 2016

VIN Range 1 : Begin :

NR

End : NR

 Not sequential**Description of Defect :**

Description of the Defect : Per GM chassis Recall 18155 (18V-295) - Under certain conditions, liquid can enter the Driver side power window switch and cause corrosion, leading to high electrical resistance.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : PER GM - High electrical resistance can cause the switch to heat up, smoke, or melt, increasing the risk of fire causing personal injury and/or property damage.

Description of the Cause : NR

Identification of Any Warning that can Occur : PER GM - occupants may notice that the power window is malfunctioning or inoperative,, Smoke or an odor from smoke or melting may also come from the door panel.

Supplier Identification :**Component Manufacturer**

Name : Chevrolet
Address : NR
FOREIGN STATES
Country : Anguilla

Chronology :

8-21-18 Received information on GM recall 18155 - with affected chassis VIN that were delivered to Jayco - Chassis Vins matched to product serial numbers 8-22-18 to create scope - 8-23-18 Safety Steering Committee discussed details and voted that a Recall was required to noted Jayco's affected product. .

Description of Remedy :

Description of Remedy Program : PER GM - GM Dealer will Replace the driver side door window switch at no charge
How Remedy Component Differs from Recalled Component : NR
Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : GM is releasing Recall notification and will provide 6 qrtly reports to NHTSA.. Jayco is filing recall to ONLY call out the serial numbers of our affected class c motorhomes.
Planned Dealer Notification Date : NR - NR
Planned Owner Notification Date : NR - NR

* NR - Not Reported