

# Part 573 Safety Recall Report

# 19V-029

**Manufacturer Name :** Double K Inc.**Submission Date :** JAN 11, 2019**NHTSA Recall No. :** 19V-029**Manufacturer Recall No. :** FL794A-V**Manufacturer Information :**

Manufacturer Name : Double K Inc.

Address : 701 North Railroad Avenue  
Crandon WI 54520

Company phone : 715-478-5090

**Population :**

Number of potentially involved : 5

Estimated percentage with defect : NR

**Vehicle Information :**

Vehicle 1 : 2017-2018 Hometown Trolley Villager, Mainstreet, Streetcar

Vehicle Type : BUSES, MEDIUM &amp; HEAVY VEHICLES

Body Style : OTHER

Power Train : GAS

Descriptive Information : Manufacturer of Trackless Trolley Buses

Production Dates : NOV 01, 2017 - OCT 16, 2018

VIN Range 1 : Begin : NR End : NR

 Not sequential**Description of Defect :**

Description of the Defect : On certain vehicles, insufficiently torqued caliper mounting bolts may not provide an adequate clamping force between the brake caliper and the brake anchor plate

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Could potentially result in reduced brake effectiveness which could increase the risk of a crash.

Description of the Cause : NR

Identification of Any Warning that can Occur : N/A

**Supplier Identification :****Component Manufacturer**

Name : Daimler Trucks North America LLC

Address : PO Box 4090  
Portland OREGON 97208  
Country : United States

### Chronology :

Notice of safety recall was sent from Daimler Trucks North America, LLC to Hometown Trolley, the manufacturer of the vehicle that uses the Freightliner chassis.

### Description of Remedy :

Description of Remedy Program : Current owners to contact an authorized Daimler Trucks North America dealer to arrange to have the recall performed and to ensure that parts are available at the dealership. To locate an authorized dealer, search online at [www.daimler-trucksnorthamerica.com](http://www.daimler-trucksnorthamerica.com). On the menu tab, select "contact" then scroll down to "find a dealer" and select the appropriate brand. Caliper mounting bolts will be inspected and torqued or replaced as needed.

How Remedy Component Differs from Recalled Component : Caliper mounting bolts FL794A-V

Identify How/When Recall Condition was Corrected in Production : Unknown

### Recall Schedule :

Description of Recall Schedule : Once approved, all 4 vendors who were identified as having chassis from this time period will be notified through mail.

Planned Dealer Notification Date : JAN 25, 2019 - FEB 15, 2019

Planned Owner Notification Date : JAN 25, 2019 - FEB 15, 2019

\* NR - Not Reported