

Part 573 Safety Recall Report

19V-092

Manufacturer Name : Oshkosh Corporation**Submission Date :** FEB 15, 2019**NHTSA Recall No. :** 19V-092**Manufacturer Recall No. :** NR**Manufacturer Information :****Population :**

Manufacturer Name : Oshkosh Corporation

Number of potentially involved : 241

Address : 2307 Oregon Street

Estimated percentage with defect : 100 %

PO Box 2566 Oshkosh WI 54903-2566

Company phone : 920-235-9151

Vehicle Information :

Vehicle 1 : 2014-2019 Oshkosh S-Series, Gliders

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : ALL

Power Train : DIESEL

Descriptive Information : All Oshkosh S-Series vehicles equipped with strobe light package in rear fender.

Production Dates : MAY 05, 2014 - SEP 06, 2018

VIN Range 1 : Begin :

NR

End : NR

 Not sequential**Description of Noncompliance :**

Description of the Noncompliance : Strobe lights were installed in the rear fender marker light position.

FMVSS 1 : 108 - Lamps, reflective devices, and assoc. Equipment

FMVSS 2 : NR

Description of the Safety Risk : The installation of the strobe light in this location does not comply to FMVSS – it may create confusion when signaling other drivers.

Description of the Cause : Incorrect lamp specified.

Identification of Any Warning that can Occur : No warning provided.

Supplier Identification :**Component Manufacturer**

Name : NR

Address : NR

Country : NR

Chronology :

Dec. 3, 2018 - Customer informs Oshkosh that they received citation for incorrect clearance lamp.
Dec. 3, 2018 - Feb. 6, 2019 - Oshkosh conducts investigation to determine which lamp was in question (limited information from customer), and responsible party for the installation of suspect lamp.
Feb. 6, 2019 - Oshkosh determines lamp was installed by Oshkosh.
Feb. 14, 2019 - Oshkosh determines lamp is not compliant to FMVSS.

Description of Remedy :

Description of Remedy Program : Oshkosh will replace lamp with conforming, steady burning lamp. Remedy will be completed at no cost to customer, and reimbursement will be made to any customer who may have had the work completed prior to notification.

How Remedy Component Differs from Recalled Component : Lamp will be red in color and steady burning.

Identify How/When Recall Condition was Corrected in Production : Strobe Lighting package was removed from production. No vehicles with option were in process.

Recall Schedule :

Description of Recall Schedule : Pending NHTSA review & approval. Oshkosh does not utilize dealers (sell factory direct to customers), no dealer notices will be issued.

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : MAR 01, 2019 - MAR 15, 2019

* NR - Not Reported