

# Part 573 Safety Recall Report

# 19V-140

**Manufacturer Name :** Midway Specialty Vehicles**Submission Date :** FEB 27, 2019**NHTSA Recall No. :** 19V-140**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Midway Specialty Vehicles

Address : 2940 Dexter Drive

Elkhart IN 46514

Company phone : 574-264-2530

**Population :**

Number of potentially involved : 1

Estimated percentage with defect : 100 %

**Vehicle Information :**

Vehicle 1 : 2016-2016 FREIGHTLINER SPRINTER

Vehicle Type : LIGHT VEHICLES

Body Style : VAN

Power Train : DIESEL

**Descriptive Information :** Ricon notified us of 1 affected lift we purchased. If the position input cam fails and the lift operator continues to press the “up” button on the operating pendant while the lift is occupied, the cutoff switch is dis-abled and the platform can travel past the vehicle floor height, potentially causing the occupant to tip inwards, toward the vehicle. If the wheelchair lift platform stops above the vehicle floor, the wheelchair user can tip inwards toward the vehicle when exiting the lift, increasing their risk of injury.

Production Dates : JUL 12, 2016 - JUL 20, 2016

VIN Range 1 : Begin : WDPPE7CD7GP207471 End : WDPPE7CD7GP207471  Not sequential**Description of Defect :**

**Description of the Defect :** If the position input cam fails and the lift operator continues to press the “up” button on the operating pendant while the lift is occupied, the cutoff switch is dis-abled and the platform can travel past the vehicle floor height, potentially causing the occupant to tip inwards, toward the vehicle. If the wheelchair lift platform stops above the vehicle floor, the wheelchair user can tip inwards toward the vehicle when exiting the lift, increasing their risk of injury.

FMVSS 1 : NR

FMVSS 2 : NR

**Description of the Safety Risk :** If the wheelchair lift platform stops above the vehicle floor, the wheelchair user can tip inwards toward the vehicle when exiting the lift, increasing their risk of injury.

**Description of the Cause :** NR

Identification of Any Warning NR  
that can Occur :

## Supplier Identification :

### Component Manufacturer

Name : Ricon Corporation  
Address : 1135 Aviation Place  
San Fernando CALIFORNIA 91340  
Country : United States

## Chronology :

NR

## Description of Remedy :

Description of Remedy Program : Ricon will provide materials and labor as outlined above through Authorized Ricon dealers.  
How Remedy Component Differs NR  
from Recalled Component :  
Identify How/When Recall Condition NR  
was Corrected in Production :

## Recall Schedule :

Description of Recall Schedule : NR  
Planned Dealer Notification Date : NR - NR  
Planned Owner Notification Date : FEB 27, 2019 - MAR 05, 2019

\* NR - Not Reported