

# Part 573 Safety Recall Report

# 18V-226

**Manufacturer Name :** Keystone RV Company**Submission Date :** APR 10, 2018**NHTSA Recall No. :** 18V-226**Manufacturer Recall No. :** 18-317**Manufacturer Information :**

Manufacturer Name : Keystone RV Company

Address : PO Box 2000  
2642 Hackberry Drive Goshen IN  
46527

Company phone : 574-535-2100

**Population :**

Number of potentially involved : 423

Estimated percentage with defect : 100 %

**Vehicle Information :**

Vehicle 1 : 2018-2018 Keystone Carbon 337, 347, 349, 357, 364, 387, 403, 417

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : All affected fifth wheels.

Production Dates : DEC 14, 2017 - MAR 23, 2018

VIN Range 1 : Begin : 4YDF35722JR805708 End : 4YDF35722JR805854  Not sequentialVehicle 2 : 2018-2018 Keystone Raptor 3018P, 3513P, 353TS, 355TS, 362TS, 398TS, 421CK,  
424TS, 425TS, 426TS, 428SP

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : All affected fifth wheels.

Production Dates : DEC 12, 2017 - MAR 23, 2018

VIN Range 1 : Begin : 4YDF35321JR800621 End : 4YDF42535JR800896  Not sequential**Description of Defect :**

Description of the Defect : It has been decided that the vehicles in the recall population may have been produced without a protective barrier in the fuel station to prevent absorption of fuel into the main floor.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : If fuel spillage occurs there is an increased risk of the main floor absorbing flammable liquids. In the presence of an ignition source there is an increased

Description of the Cause : risk of fire or personal injury.  
The protective barrier in the fuel station may not have been installed on all units due to an improperly trained installer in production.

Identification of Any Warning that can Occur : None

## Supplier Identification :

### Component Manufacturer

Name : NR  
Address : NR  
NR  
Country : NR

## Chronology :

3/23/2018 – It was discovered during an audit in production it was that the protective barrier that separates the main floor from the fuel station was missing. All units were quarantined and repaired. An investigation was opened to determine the scope and range.

4/3/2018 – Investigation completed, scope and range determined.

## Description of Remedy :

Description of Remedy Program : The remedy is to inspect for the protective barrier, if the protective barrier is missing, one will need to be installed as directed.

How Remedy Component Differs from Recalled Component : NA

Identify How/When Recall Condition was Corrected in Production : Units were quarantined, inspected then repaired as indicated by inspection.

## Recall Schedule :

Description of Recall Schedule : Keystone will notify the dealers and owners of the recreational vehicles by letter. A final copy of the owner letter will be provided to NHTSA, along with the dealer repair procedures.

Planned Dealer Notification Date : JUN 10, 2018 - JUN 10, 2018

Planned Owner Notification Date : JUN 10, 2018 - JUN 10, 2018

\* NR - Not Reported