

# Part 573 Safety Recall Report

# 18V-283

**Manufacturer Name :** Gulf Stream Coach, Inc.

**Submission Date :** APR 06, 2018

**NHTSA Recall No. :** 18V-283

**Manufacturer Recall No. :** 04052018



## Manufacturer Information :

**Manufacturer Name :** Gulf Stream Coach, Inc.

**Address :** P. O. Box 1005  
503 S. Oakland Avenue Nappanee IN  
46550

**Company phone :** 999-999-9999

## Population :

**Number of potentially involved :** 25

**Estimated percentage with defect :** 100 %

## Vehicle Information :

**Vehicle 1 :** 2017-2018 Conquest Class "C" Motor 6280

**Vehicle Type :** BUSES, MEDIUM & HEAVY VEHICLES

**Body Style :** OTHER

**Power Train :** GAS

**Descriptive Information :** Research of the Gulf Stream Coach, Inc. internal Federal Certification database identified the cause and scope of initiating this recall due to an incorrect configuration number having been used when identifying the chassis platform used in the manufacturing of the specific model 6280 the motor home. Correct model 6280 certification labels have the correct Ford chassis identified.

**Production Dates :** MAR 08, 2016 - SEP 11, 2017

**VIN Range 1 : Begin :** 1FDWE3FLOGDC40209 **End :** 1FDWE3FS0HDC66687  Not sequential

## Description of Defect :

**Description of the Defect :** On certain model 6280 Conquest Class C Motor Homes manufactured by Gulf Stream Coach, Inc. ("GulfStream") the Federal Certification label and accompanying Motor Home Weight Information Label incorrectly identifies the Ford chassis as an E450 14,500 lb. GVWR when the motor home was built on the E350 Ford chassis 12,500 lb. GVWR.

**FMVSS 1 :** 567 - Certification

**FMVSS 2 :** NR

**Description of the Safety Risk :** Relying on the incorrect GVWR may lead to possible overloading of the vehicle which may lead to poor handling characteristics, which could result in a crash causing property damage and/or personal injury.

**Description of the Cause :** During the paperwork preparation process, Gulf Stream referenced an incorrect configuration number when generating the labels, thereby printing and releasing the incorrect information on the labels applied to and provided

with the motor home. These incorrect labels were not identified prior to shipping the motor home.

Identification of Any Warning that can Occur : Unknown

## Supplier Identification :

### Component Manufacturer

Name : NR  
Address : NR  
NR  
Country : NR

## Chronology :

During the paperwork preparation process, Gulf Stream referenced an incorrect configuration number when generating the labels, thereby printing and releasing the incorrect information on the labels applied to and provided with the motor home.

## Description of Remedy :

Description of Remedy Program : Updated labels and accompanying paperwork will be mailed to owners of the affected model 6280 Motor Homes along with instructions for proper installation.

How Remedy Component Differs from Recalled Component : Paperwork discrepancy only which inaccurately identifies the chassis as being an E450 on Certification labels installed. The E350 Ford chassis as Gulf Stream Coach manufactured the motor home on is the correct chassis for the 6280 model.

Identify How/When Recall Condition was Corrected in Production : Immediately.  
Any finished goods in our possession were held from shipping and corrected labels were applied prior to shipping.

## Recall Schedule :

Description of Recall Schedule : Replacement labels are ready to mail upon approval and receipt of a Recall number assigned to this recall.

Planned Dealer Notification Date : APR 09, 2018 - APR 13, 2018

Planned Owner Notification Date : APR 09, 2018 - APR 30, 2018

\* NR - Not Reported