

Part 573 Safety Recall Report

18V-286

Manufacturer Name : Jayco, Inc.**Submission Date :** MAY 03, 2018**NHTSA Recall No. :** 18V-286**Manufacturer Recall No. :** 9901377**Manufacturer Information :**

Manufacturer Name : Jayco, Inc.

Address : 903 South Main Street

PO Box 460 Middlebury IN 46540

Company phone : 800-283-8267

Population :

Number of potentially involved : 610

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2018-2018 Fifth Wheel Eagle HT w optional bin box

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Production records of all 2018 Models of Eagle HT Fifth wheels built with the MOrRyde 16K Orbital Pin box - this option was not available prior to 1-1-2018

Products not affected by recall have 16K Orbital Pin box manufactured after the issue was discovered and corrected

Production Dates : JAN 01, 2018 - APR 27, 2018

VIN Range 1 : Begin :

NR

End : NR

 Not sequential**Description of Defect :**

Description of the Defect : 1/8" variation in the welding of the spindle during MOrRyde manufacturing process of the 16K Orbital Pin Box - metal to metal contact

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Pin box may lock out at 180 degrees (straight) , not pivoting as specified at 90 degrees. - metal to metal may reduce durability - increasing risk of crash when unit is being towed

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : MorRyde International
Address : 1966 Sterling Ave
Elkhart INDIANA 46516
Country : United States

Chronology :

4-25-18 MOrRyde notified Jayco of a manufacturing defect in their 16K capacity Orbital Pin box. MOrRyde noted they would be filing recall. MOrRyde immediately started repairs product on site and their inventory, 4-26-18 Jayco Safety Committee reviewed all details of the matter and decided that a safety recall is required.

Description of Remedy :

Description of Remedy Program : Addition of spacer to correct the spacing error.
How Remedy Component Differs from Recalled Component : NR
Identify How/When Recall Condition was Corrected in Production : Per MOrRyde - correction started 4-25-18 in their manufacturing facility and MOrRyde was on site at Jayco 4-25-18 to repair all units still on site with the optional pin box

Recall Schedule :

Description of Recall Schedule : We are still working with MOrRyde on parts availability and repair instructions for release of the recall.
Planned Dealer Notification Date : JUL 03, 2018 - JUL 03, 2018
Planned Owner Notification Date : JUL 03, 2018 - JUL 03, 2018

* NR - Not Reported