

Part 573 Safety Recall Report

18V-294

Manufacturer Name : Starcraft RV**Submission Date :** MAY 03, 2018**NHTSA Recall No. :** 18V-294**Manufacturer Recall No. :** 9902379**Manufacturer Information :**

Manufacturer Name : Starcraft RV

Address : 903 South Main Street

P.O. Box 460 Middlebury IN 46540

Company phone : 800-945-4787

Population :

Number of potentially involved : 102

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2011-2013 Camping Trailer Starcraft and Comet

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : ONLY 2011 and 2013 model years are affected - 2011 Starcraft BC BD Models and Comet BA BB BC Production reports noted camping trailers manufactured with Lippert Power Roof Lift Mechanism

2011 Starcraft 1020 BC

1223 BD

2013 Comet 816 BA

1019 BB

1020 BC

Production Dates : AUG 02, 2010 - AUG 09, 2012

VIN Range 1 : Begin : NR

End : NR

 Not sequential**Description of Defect :**

Description of the Defect : Mis-use of the manual over-ride feature on the Lippert Power Roof Lift Mechanism could create higher torque values thru the drive motor. Higher torque values may damage components

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : High torque may damage the lift mechanism which could allow the roof to collapse (fall) and could result in severe personal injury and/or property damage,

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : NR
Address : NR
NR
Country : NR

Chronology :

During investigation of a reported roof collapse on a 2013 Jayco Series Camping Trailer, it was discovered that the failure was due to the mis- use of the manual override. 4-26-18 Safety Committee reviewed details of incident and decided that a safety recall was required.

Description of Remedy :

Description of Remedy Program : Place Warning Label on affected units in close proximity of the manual over-ride feature to alert consumer of risk and proper use - copy of WARNING label downloaded with 573

How Remedy Component Differs from Recalled Component : presence of WARNING Label on the camping trailer

Identify How/When Recall Condition was Corrected in Production : System no longer used in current production of camping trailers.

Recall Schedule :

Description of Recall Schedule : Confirming availability of Warning label to enclose with recall notification to current owner on record.

Planned Dealer Notification Date : JUL 03, 2018 - JUL 03, 2018

Planned Owner Notification Date : JUL 03, 2018 - JUL 03, 2018

* NR - Not Reported