

Part 573 Safety Recall Report

18V-310

Manufacturer Name : Trail Boss Conversions, Inc.

Submission Date : MAY 14, 2018

NHTSA Recall No. : 18V-310

Manufacturer Recall No. : NR



Manufacturer Information :

Manufacturer Name : Trail Boss Conversions, Inc.

Address : 308 W US HWY 40

BATES CITY MO 64011

Company phone : 816-690-7133

Population :

Number of potentially involved : 1

Estimated percentage with defect : 100 %

Vehicle Alterer Information :

Vehicle 1 : 2017-2017 Twister Horse Trailer

Descriptive Information : We put the living quarters conversion in 1 Twister horse trailer that had a recall on the Norcold refrigerator that was installed in this unit.

Production Dates : DEC 08, 2017 - JAN 12, 2018

Description of Defect :

Description of the Defect : Norcold determined that certain gas valves on the N306 refrigerators were exhibiting low flow and adjustments were being made to an unused connection on the propane gas valve of these refrigerators. This unused connection may have been loosened during Norcold's manufacturing testing process. If the refrigerator is set to operate on propane, leaking propane may cause a fire.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : If the refrigerator is set to operate on propane, leaking propane may cause a fire.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :

Component Manufacturer

Name : Norcold Inc.

Address : 600 S Kuther Rd

Sidney OHIO 45365
Country : United States

Chronology :

Norcold advised Trail Boss Conversions, Inc. of its defect determination via certified mail May 8th, 2018 with the recall #18E018. Trail Boss is not aware of any injuries in its vehicle that appear to be related to this defect.

Description of Remedy :

Description of Remedy Program : Norcold Inc. has arranged to conduct a recall to remedy the potential defect in the Trail Boss Conversions, Inc. vehicle at no charge to the vehicle owner. See Recall 18E013. Customer is to locate a service center near them by going to www.norcoldrecall.com. The inspection and testing of the tightness of the fitting will be done at not cost to the customer.

How Remedy Component Differs
from Recalled Component : NR

Identify How/When Recall Condition
was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : Trail Boss Conversions, Inc. will send out the dealer notification letter certified mail on May 25, 2018 if the letter is approved. There will be no owner notification letter because the dealer that we installed the living quarters into the Twister trailer for has not sold the trailer yet, so the dealer currently owns the trailer.

Planned Dealer Notification Date : MAY 25, 2018 - MAY 25, 2018

Planned Owner Notification Date : NR - NR

Purchaser Information :

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name :

Address :

Country :

Company Phone :

* NR - Not Reported