

Part 573 Safety Recall Report

18V-313

Manufacturer Name : Keystone RV Company

Submission Date : MAY 14, 2018

NHTSA Recall No. : 18V-313

Manufacturer Recall No. : 18-320



Manufacturer Information :

Manufacturer Name : Keystone RV Company

Address : PO Box 2000
2642 Hackberry Drive Goshen IN
46527

Company phone : 574-535-2100

Population :

Number of potentially involved : 313

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2018-2018 Keystone Montana: All Models

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : All Montana fifth wheels

Production Dates : JAN 31, 2018 - FEB 26, 2018

VIN Range 1 : Begin : 4YDF38229J4703490 **End :** 4YDF3722XJ4703802 **Not sequential**

Description of Defect :

Description of the Defect : It has been decided that the vehicles in the recall population may have a slide out switch that does not have circuit protection as required.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Under certain conditions, if the slide out wire shorts to ground it can lead to an increased risk of damage or fire.

Description of the Cause : The slide out switch wiring was incorrectly wired without circuit protection when connecting the slide out switch wiring to the 10 gauge power source wire.

Identification of Any Warning that can Occur : Loss of slide room function, or visible damage to the wiring.

Supplier Identification :

Component Manufacturer

Name : NR
Address : NR
NR
Country : NR

Chronology :

3/2/2018 – Report was made that a new employee was incorrectly wiring the slide out switch. Units in our possession were repaired before shipping.
3/4/2018 – Investigation opened. All affected Montana units were put on hold and wiring was repaired.
5/8/2018 – Investigation concluded and scope completed.

Description of Remedy :

Description of Remedy Program : The remedy is to disconnect the wiring at the power source wire and correctly install the provided inline fuse.
How Remedy Component Differs from Recalled Component : N/A
Identify How/When Recall Condition was Corrected in Production : Units were quarantined, inspected then repaired as indicated by inspection.

Recall Schedule :

Description of Recall Schedule : Keystone will notify the dealers and owners of the recreational vehicles by letter. A final copy of the owner letter will be provided to NHTSA, along with the dealer repair procedures.
Planned Dealer Notification Date : JUL 08, 2018 - JUL 08, 2018
Planned Owner Notification Date : JUL 08, 2018 - JUL 08, 2018

* NR - Not Reported