

Part 573 Safety Recall Report

18V-383

Manufacturer Name : Keystone RV Company**Submission Date :** JUN 07, 2018**NHTSA Recall No. :** 18V-383**Manufacturer Recall No. :** 18-322**Manufacturer Information :**

Manufacturer Name : Keystone RV Company

Address : PO Box 2000
2642 Hackberry Drive Goshen IN
46527

Company phone : 574-535-2100

Population :

Number of potentially involved : 5,107

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2018-2019 Keystone Cougar 25RES, 26RBS, 26RKS, 27RES, 29BHS, 29RDB, 29RKS, 32BHS, 32DBH, 32RDB, 338RLK, 33MLS, 34TSB, 368MBI, 369BHS, 25BHSWE, 25RESWE, 26RBSWE, 27RESWE, 29BHSWE, 29RDBWE, 30RKSWE, 31BHKWE

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Models with outdoor propane grill.

Production Dates : JUL 25, 2017 - MAY 22, 2018

VIN Range 1 : Begin : 4YDF36820J2503430 End : 4YDT32R22JV513269

 Not sequential

VIN Range 2 : Begin : 4YDF32B25K2500235 End : 4YDT26R25KV501824

 Not sequential**Description of Defect :**

Description of the Defect : It has been decided that the vehicles in the recall population have an outdoor propane grill installed with clearances that are no longer within the grill manufacturer's specified tolerances to combustible material.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Under certain conditions when using the outside propane grill it is possible for the wooden assembly the grill is installed in to be exposed to elevated temperatures leading to an increased risk of fire.

Description of the Cause : Approximately six months after production began installing this grill, the grill manufacturer's installation specifications changed.

Identification of Any Warning that can Occur : Smoke or discoloring of the wooden assembly.

Supplier Identification :**Component Manufacturer**

Name : NR
Address : NR
NR
Country : NR

Chronology :

4/30/2018 – A warranty claim was received for an outdoor grill with heat damage to the wooden assembly it is mounted in.
5/1/2018 – Vendor contacted and investigation initiated.
5/31/2018 – Investigation concluded and scope completed.

Description of Remedy :

Description of Remedy Program : The remedy is to replace the wood assembly with a metal assembly.
How Remedy Component Differs from Recalled Component : The remedy component is not a combustible material.
Identify How/When Recall Condition was Corrected in Production : Units were quarantined, inspected then repaired as indicated by inspection.

Recall Schedule :

Description of Recall Schedule : Keystone will notify the dealers and owners of the recreational vehicles by letter. A final copy of the owner letter will be provided to NHTSA, along with the dealer repair procedures.
Planned Dealer Notification Date : JUL 31, 2018 - JUL 31, 2018
Planned Owner Notification Date : JUL 31, 2018 - JUL 31, 2018

* NR - Not Reported