

# Part 573 Safety Recall Report

# 18V-429

**Manufacturer Name :** Keystone RV Company

**Submission Date :** JUN 25, 2018

**NHTSA Recall No. :** 18V-429

**Manufacturer Recall No. :** 18-324



## Manufacturer Information :

**Manufacturer Name :** Keystone RV Company

**Address :** PO Box 2000  
2642 Hackberry Drive Goshen IN  
46527

**Company phone :** 574-535-2100

## Population :

**Number of potentially involved :** 20

**Estimated percentage with defect :** 100 %

## Vehicle Information :

**Vehicle 1 :** 2019-2019 Keystone Summerland 2020QB

**Vehicle Type :** TRAILERS

**Body Style :**

**Power Train :** NR

**Descriptive Information :** Units in production during a supplier change.

**Production Dates :** MAY 22, 2018 - MAY 30, 2018

**VIN Range 1 : Begin :** 4YDT20224K3150617 **End :** 4YDT20226K3150697  Not sequential

## Description of Noncompliance :

**Description of the Noncompliance :** It has been decided that the vehicles in the recall population fail to conform to the requirements of Part 567, "Certification." The vehicles subject to this recall may have been manufactured with the incorrect information on the Federal Identification Tag. The tag indicates the rim size is 15X6. The correct rim size is 15X5.

**FMVSS 1 :** 567 - Certification

**FMVSS 2 :** NR

**Description of the Safety Risk :** Fails to conform to the requirements of Part 567, "Certification."

**Description of the Cause :** The incorrect rim size was printed on the label.

**Identification of Any Warning that can Occur :** Rim size on the Federal Identification Tag does not match information for the rim.

## Supplier Identification :

**Component Manufacturer**

Name : NR  
Address : NR  
NR  
Country : NR

**Chronology :**

June 12, 2018 – Production noted the label was incorrect for the rim size.  
June 21, 2018 – Investigation concluded and scope completed. Determined the Federal Identification Tag would need to be replaced.

**Description of Remedy :**

Description of Remedy Program : The remedy is to replace the Federal Identification Tag.  
How Remedy Component Differs from Recalled Component : The repair will conform to requirements of Part 567, "Certification."  
Identify How/When Recall Condition was Corrected in Production : Units were quarantined, inspected then repaired as indicated by inspection.

**Recall Schedule :**

Description of Recall Schedule : Keystone will notify the dealers and owners of the recreational vehicles by letter. A final copy of the owner letter will be provided to NHTSA, along with the dealer repair procedures.  
Planned Dealer Notification Date : AUG 21, 2018 - AUG 21, 2018  
Planned Owner Notification Date : AUG 21, 2018 - AUG 21, 2018

\* NR - Not Reported