

Part 573 Safety Recall Report

18V-448

Manufacturer Name : Keystone RV Company**Submission Date :** JUL 05, 2018**NHTSA Recall No. :** 18V-448**Manufacturer Recall No. :** 18-325**Manufacturer Information :**

Manufacturer Name : Keystone RV Company

Address : PO Box 2000
2642 Hackberry Drive Goshen IN
46527

Company phone : 574-535-2100

Population :

Number of potentially involved : 83

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2018-2019 Dutchmen Aerolite 2133RB, 2423BH

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Units with incorrect tire rim size on Federal Identification Tag.

Production Dates : MAR 02, 2018 - JUN 14, 2018

VIN Range 1 : Begin : 4YDT24224JP910978 End : 4YDT2132XP911095

 Not sequential

VIN Range 2 : Begin : 4YDT24225KP910005 End : 4YDT24223KP910374

 Not sequential**Description of Noncompliance :**

Description of the Noncompliance : It has been decided that the vehicles in the recall population fail to conform to the requirements of Part 567, "Certification." The vehicles subject to this recall may have been manufactured with the incorrect information on the Federal Identification Tag. The tag indicates the rim size is 14X5.5J. The correct rim size is 14X5J.

FMVSS 1 : 567 - Certification

FMVSS 2 : NR

Description of the Safety Risk : Fails to conform to the requirements of Part 567, "Certification."

Description of the Cause : The incorrect rim size was printed on the label.

Identification of Any Warning that can Occur : Rim size on the Federal Identification Tag does not match information for the rim.

Supplier Identification :

Component Manufacturer

Name : NR
Address : NR
NR
Country : NR

Chronology :

June 25, 2018 – Production noted the label was incorrect for the rim size.
July 2, 2018 – Investigation concluded and scope completed. Determined the Federal Identification Tag would need to be replaced.

Description of Remedy :

Description of Remedy Program : The remedy is to replace the Federal Identification Tag.
How Remedy Component Differs from Recalled Component : The repair will conform to requirements of Part 567, "Certification."
Identify How/When Recall Condition was Corrected in Production : Units were quarantined, inspected then repaired as indicated by inspection.

Recall Schedule :

Description of Recall Schedule : Keystone will notify the dealers and owners of the recreational vehicles by letter. A final copy of the owner letter will be provided to NHTSA, along with the dealer repair procedures.
Planned Dealer Notification Date : SEP 02, 2018 - SEP 02, 2018
Planned Owner Notification Date : SEP 02, 2018 - SEP 02, 2018

* NR - Not Reported