

# Part 573 Safety Recall Report

# 18V-460

**Manufacturer Name :** Jayco, Inc.**Submission Date :** JUL 11, 2018**NHTSA Recall No. :** 18V-460**Manufacturer Recall No. :** 9901406**Manufacturer Information :**

Manufacturer Name : Jayco, Inc.

Address : 903 South Main Street

PO Box 460 Middlebury IN 46540

Company phone : 800-283-8267

**Population :**

Number of potentially involved : 62

Estimated percentage with defect : 100 %

**Vehicle Information :**

Vehicle 1 : 2018-2018 Travel Trailer Octane VH VF

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Production records of ALL 2018 noting BOM with optional Generator  
J1VF0135-0152 J1VH0053-0060 0062-0067 0069-0098 0100-0110

Production Dates : JUN 08, 2017 - MAR 29, 2018

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Vehicle 2 : 2018-2018 Jayco travel trailer Octane VF VH

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Production records of all Octanes built with optional Generator - other Octanes not  
affected were built standard without the Generator.

Production Dates : JUN 08, 2017 - MAR 29, 2018

VIN Range 1 : Begin :

NR

End : NR

 Not sequential**Description of Defect :**Description of the Defect : Generator Exhaust pipe was inadvertently omitted in manufacturing process of  
the travel trailer

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Exhaust from the generator may enter the trailer and create a life threatening  
condition for occupants.

Description of the Cause : Supplier shortage of exhaust pipe was not noted on internal shortage report and units were released to ship in error.

Identification of Any Warning NR  
that can Occur :

## Supplier Identification :

### Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

## Chronology :

7-2-18 Sales received call from dealer stating he had two "VH" Octane travel trailers that did not have the exhaust on the generator. - 7-2-18 information was passed on for research of claims / contacts -reviewed 2017-2018 7-3-18 found 5 2018 VH units noting a missing generator exhaust pipe. and 3 2018 VF models including another model of Octane VF 7-2-18 all 2019 models of Octane travel trailers on site were inspected and found to have the generator exhaust pipe installed. 7-5-18 an emergency meeting called of the Safety Steering Committee to review details of incident - members voted that a safety recall was required.

## Description of Remedy :

Description of Remedy Program : Inspection of unit to confirm if generator exhaust pipe is installed, IF NOT, Dealer will install exhaust pipe per instructions.

How Remedy Component Differs NR  
from Recalled Component :

Identify How/When Recall Condition NR  
was Corrected in Production :

## Recall Schedule :

Description of Recall Schedule : Jayco is prepared to release recall immediately upon receipt of exhaust pipe from vendor and Recall number from NHTSA.

Planned Dealer Notification Date : JUL 30, 2018 - JUL 30, 2018

Planned Owner Notification Date : JUL 30, 2018 - JUL 30, 2018

\* NR - Not Reported