

Part 573 Safety Recall Report

18V-518

Manufacturer Name : Newmar Corporation**Submission Date :** AUG 06, 2018**NHTSA Recall No. :** 18V-518**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Newmar Corporation

Address : 355 North Delaware Street

PO Box 30 Nappanee IN 46550

Company phone : 574-773-7791

Population :

Number of potentially involved : 239

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2018-2019 Newmar Ventana LE

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, the entrance door latch may not be adjusted correctly. If the entrance door is not adjusted correctly, even if the door is locked, the door could possibly open unintentionally. If the door opens while driving, this could increase the risk of injury and/or property damage. Dealers will adjust the door latch to function correctly.

Production Dates : JAN 10, 2018 - APR 06, 2018

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Vehicle 2 : 2018-2019 Newmar Mountain Aire

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, the entrance door latch may not be adjusted correctly. If the entrance door is not adjusted correctly, even if the door is locked, the door could possibly open unintentionally. If the door opens while driving, this could increase the risk of injury and/or property damage. Dealers will adjust the door latch to function correctly.

Production Dates : JAN 10, 2018 - APR 06, 2018

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Vehicle 3 : 2018-2019 Newmar Essex

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, the entrance door latch may not be adjusted correctly. If the entrance door is not adjusted correctly, even if the door is locked, the door could possibly open unintentionally. If the door opens while driving, this could increase the risk of injury and/or property damage. Dealers will adjust the door latch to function correctly.

Production Dates : JAN 10, 2018 - APR 06, 2018

VIN Range 1 : Begin : NR **End :** NR Not sequential

Vehicle 4 : 2018-2019 Newmar Ventana

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, the entrance door latch may not be adjusted correctly. If the entrance door is not adjusted correctly, even if the door is locked, the door could possibly open unintentionally. If the door opens while driving, this could increase the risk of injury and/or property damage. Dealers will adjust the door latch to function correctly.

Production Dates : JAN 10, 2018 - APR 06, 2018

VIN Range 1 : Begin : NR **End :** NR Not sequential

Vehicle 5 : 2018-2019 Newmar Dutch Star

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, the entrance door latch may not be adjusted correctly. If the entrance door is not adjusted correctly, even if the door is locked, the door could possibly open unintentionally. If the door opens while driving, this could increase the risk of injury and/or property damage. Dealers will adjust the door latch to function correctly.

Production Dates : JAN 10, 2018 - APR 06, 2018

VIN Range 1 : Begin : NR **End :** NR Not sequential

Vehicle 6 : 2018-2019 Newmar New Aire

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, the entrance door latch may not be adjusted correctly. If the entrance door is not adjusted correctly, even if the door is locked, the door could possibly open unintentionally. If the door opens while driving, this could increase the risk of injury and/or property damage. Dealers will adjust the door latch to function correctly.

Production Dates : JAN 10, 2018 - APR 06, 2018

VIN Range 1 : Begin : NR **End :** NR Not sequential

Vehicle 7 : 2018-2019 Newmar London Aire
Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES
Body Style :
Power Train : NR

Descriptive Information : On certain motorhomes, the entrance door latch may not be adjusted correctly. If the entrance door is not adjusted correctly, even if the door is locked, the door could possibly open unintentionally. If the door opens while driving, this could increase the risk of injury and/or property damage. Dealers will adjust the door latch to function correctly.

Production Dates : JAN 10, 2018 - APR 06, 2018

VIN Range 1 : Begin : NR **End :** NR Not sequential

Vehicle 8 : 2018-2019 Newmar King Aire
Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES
Body Style :
Power Train : NR

Descriptive Information : On certain motorhomes, the entrance door latch may not be adjusted correctly. If the entrance door is not adjusted correctly, even if the door is locked, the door could possibly open unintentionally. If the door opens while driving, this could increase the risk of injury and/or property damage. Dealers will adjust the door latch to function correctly.

Production Dates : JAN 10, 2018 - APR 06, 2018

VIN Range 1 : Begin : NR **End :** NR Not sequential

Description of Defect :

Description of the Defect : The entrance door latch may not be adjusted correctly. If the entrance door is not adjusted correctly, even if the door is locked, the door could possibly open unintentionally.

FMVSS 1 : NR

FMVSS 2 : 206 - Door locks and door retention components

Description of the Safety Risk : If the door opens while driving, this could increase the risk of injury and/or property damage. Dealers will adjust the door latch to function correctly.

Description of the Cause : Entry door lock out of adjustment.

Identification of Any Warning that can Occur : None

Supplier Identification :

Component Manufacturer

Name : PTL Engineering
Address : 3333 John Conley Dr.
Lapeer MICHIGAN 48446
Country : United States

Chronology :

On 6/28/2018 Newmar received notice of possible issue with entry door latch out of adjustment. On 7/31/2018, a decision was made to file notice of defect. 08/06/2018, Newmar is giving notice to NHTSA for a safety recall.

Description of Remedy :

Description of Remedy Program : Dealers will adjust the door latch to function correctly at no cost to the customer.

How Remedy Component Differs from Recalled Component : Entry door lock will be adjusted on same door.

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : On or before 10/05/2018, customer/dealer letters will be sent out.

Planned Dealer Notification Date : OCT 05, 2018 - OCT 05, 2018

Planned Owner Notification Date : OCT 05, 2018 - OCT 05, 2018

* NR - Not Reported