

Part 573 Safety Recall Report

18V-577

Manufacturer Name : Brown Industries, LLC

Submission Date : AUG 30, 2018

NHTSA Recall No. : 18V-577

Manufacturer Recall No. : NR



Manufacturer Information :

Manufacturer Name : Brown Industries, LLC

Address : 807 E 29TH Street

Lawrence KS 66046

Company phone : 999

Population :

Number of potentially involved : 4

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2017-2018 American Heritage Trolley 26ft ADA -35ft ADA

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : UNKNOWN

Power Train : GAS

Descriptive Information : There are four affected vehicles. Two Ford F53 chassis and two Freightliner MB65 chassis. All have the Ricon lift that is being recalled.

Chassis VIN's

Ford 1F66F5DY1G0A12225

Ford 1F66F5DY2J0A09504

Freightliner 4UZADEFD1JCJV5734

Freightliner 4UZADEFD3JCJV5735

Production Dates : JAN 01, 2017 - AUG 30, 2018

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Description of Defect :

Description of the Defect : Position input cam fails on approximately 4,262 Ricon S Series and K Series Titanium Wheelchair Lifts, part numbers K200, K201, K550, K551, S200, S201, S550, S551.

FMVSS 1 : 403 - Platform lift systems

FMVSS 2 : NR

Description of the Safety Risk : If the position input cam fails and the lift operator continues to press the "up" button on the operating pendant while the lift is occupied, the cutoff switch is disabled and the platform can travel past the vehicle floor height, potentially causing the occupant to tip inwards, toward the vehicle.

Description of the Cause : If the position input cam fails and the lift operator continues to press the "up" button on the operating pendant while the lift is occupied, the cutoff switch is disabled and the platform can travel past the vehicle floor height, potentially

causing the occupant to tip inwards, toward the vehicle.

Identification of Any Warning NR
that can Occur :

Supplier Identification :

Component Manufacturer

Name : Ricon Corporation, a Wabtec Company
Address : 1135 Aviation Place
San Fernando CALIFORNIA 91340
Country : United States

Chronology :

Received notice of recall from Ricon Coproration.

Description of Remedy :

Description of Remedy Program : Ricon will provide instructions and materials for replacing defective parts. This remediation is to be conducted by Ricon Authorized dealers or Ricon personnel only.

How Remedy Component Differs Unsure
from Recalled Component :

Identify How/When Recall Condition was Corrected in Production : Ricons notice says the "The recall population includes all units of these models beginning January 1, 2012, until May 9, 2018."

Recall Schedule :

Description of Recall Schedule : Once Brown Industries letter is approved we will mail it out within 4 days.
Planned Dealer Notification Date : SEP 04, 2018 - SEP 07, 2018
Planned Owner Notification Date : SEP 07, 2018 - SEP 28, 2018

* NR - Not Reported