

Part 573 Safety Recall Report

18V-584

Manufacturer Name : Collins Bus Corporation**Submission Date :** SEP 04, 2018**NHTSA Recall No. :** 18V-584**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Collins Bus Corporation

Address : P.O. Box 2946
Hutchinson KS 67504

Company phone : 9999

Population :

Number of potentially involved : 59

Estimated percentage with defect : 90 %

Vehicle Information :

Vehicle 1 : 2012-2018 Collins School Bus

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : NR

Descriptive Information : 59 Collins Buses are equipped with Ricon S and K Series wheelchair lifts, the affected part numbers are K200, K201, K550, K551, S200, S201, S550, S551

Production Dates : JAN 01, 2012 - AUG 24, 2018

VIN Range 1 : Begin : NR End : NR

 Not sequential**Description of Defect :**

Description of the Defect : If the position input cam fails on the Ricon Wheelchair lift and the operator continues to press the "up" button on the operating pendant while the lift is occupied, the cutoff switch is dis-abled, and the platform can travel past the vehicle floor height, potentially causing the occupant to tip inwards, toward the vehicle.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : If the wheelchair lift platform stops above the vehicle floor, the wheelchair user can tip inwards toward the vehicle when exiting the lift, increasing their risk of injury.

Description of the Cause : NR

Identification of Any Warning NR
that can Occur :

Supplier Identification :

Component Manufacturer

Name : Ricon Corporation
Address : 1135 Aviation Place
San Fernando CALIFORNIA 91340
Country : United States

Chronology :

Collins bus was notified on August 24, 2018 of Ricon recall 18E-044, upon receiving the owner notification letter, the decision to file a 573 report for Collins Bus was made.

Description of Remedy :

Description of Remedy Program : Ricon does not currently have a remedy. Owners may contact Ricon customers service at 1-800-322-2884 or by emailing the Ricon Recall coordinator at Admin18E044@wabtec.com. Ricon will provide materials and labor through authorized Ricon dealers.

How Remedy Component Differs
from Recalled Component : NR

Identify How/When Recall Condition
was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : We will need information from Ricon to know when the remedy will be available. For now we will plan on notifying owners within 60 days.
Planned Dealer Notification Date : NR - NR
Planned Owner Notification Date : OCT 25, 2018 - OCT 26, 2018

* NR - Not Reported