

Part 573 Safety Recall Report

18V-596

Manufacturer Name : Corp. Micro Bird Inc.

Submission Date : SEP 07, 2018

NHTSA Recall No. : 18V-596

Manufacturer Recall No. : 18-076-IUS



Manufacturer Information :

Manufacturer Name : Corp. Micro Bird Inc.

Address : 3000, Rue Girardin

Drumondville, Quebec 00 J2E 0A1

Company phone : 819-477-2012

Population :

Number of potentially involved : 252

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2018-2018 Micro Bird MBII

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : School Bus Seat, NextGen Series W/ Integrated Child Restraint System – Warning Label

Production Dates : JAN 15, 2018 - JUL 25, 2018

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Description of Noncompliance :

Description of the Noncompliance : HSM Solutions has determined that NextGen School Bus Seats equipped with an Integrated Child Restraint Belt System, as manufactured by HSM Solutions, do not comply with the labeling requirements of CFR 49.571.213. Specifically, the warning label required by paragraph S5.5.4 (g) (1), of the regulation

FMVSS 1 : 213 - Child restraint systems

FMVSS 2 : NR

Description of the Safety Risk : HSM has determined that there may be an increased risk of Death or injury, if the Child Restraint Belt System is improperly used. Risk of injury may occur during a hard braking and/or a crash event.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :

Component Manufacturer

Name : HSM Transportation Solutions
Address : 417 N. Kibler Street
New Washington OHIO 44854
Country : United States

Chronology :

Micro Bird have received a preliminary safety recall notice from HSM Transportation Solutions on August 22, 2018. Following the reception on September 5, 2018 of a communication from NHTSA, it was decided on September 7, 2018 that the vehicles matched with the recalled seats shall be recalled.

No report, accident, injury or fatality has been reported to Micro Bird regarding the situation.

Description of Remedy :

Description of Remedy Program : HSM Transportation Solutions will provide parts and a Service Repair Procedure "SRP" to mitigate this recall at no charge. It will be the responsibility of the lift owners to execute the mitigation

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : OCT 08, 2018 - OCT 22, 2018

Planned Owner Notification Date : OCT 22, 2018 - NOV 05, 2018

* NR - Not Reported