

Part 573 Safety Recall Report

18V-618

Manufacturer Name : Jayco, Inc.**Submission Date :** SEP 12, 2018**NHTSA Recall No. :** 18V-618**Manufacturer Recall No. :** 9901410**Manufacturer Information :**

Manufacturer Name : Jayco, Inc.

Address : 903 South Main Street

PO Box 460 Middlebury IN 46540

Company phone : 800-283-8267

Population :

Number of potentially involved : NR

Estimated percentage with defect : NR

Vehicle Information :

Vehicle 1 : 2019-2019 Travel Trailer White Hawk , Jay Flight, Jay Flight SLX

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Dexter PO report of recalled axle serial numbers was compared to Production reports to note units manufactured on the recalled axles. We are finalizing the scope will add number of units and specific unit serial number information as available.

Production Dates : JUN 20, 2018 - JUL 31, 2018

VIN Range 1 : Begin :

NR

End : NR

 Not sequential**Description of Defect :**

Description of the Defect : Per Dexter, the D44 axles manufacture 6-20-18 thru 7-31-18 may be missing inner bearing races on the hubs.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Premature bearing failure, which could lead to separation of the hub from the axle, creating a safety hazard.

Description of the Cause : Bearing cap was not installed in hub during Dexter manufacturing process.

Identification of Any Warning that can Occur : Per Dexter, if bearing cap is missing, hub may initially heat up. If this were to occur, hub may start to smoke from bearing grease. Wheel may become wobbly if bearing starts to fail.

Supplier Identification :

Component Manufacturer

Name : Dexter Axle Company
Address : 2900 Industrial Parkway East
Elkhart INDIANA 46516
Country : United States

Chronology :

8-23-18 Dexter met with Jayco Corp to inform of issue with D44 axles manufactured without a bearing cup on hubs. Dexter submitted list of axles delivered to Jayco Divisions with in time frame of 6-20-18 thru 7-31-18. Jayco Corp. Safety Steering Committee reviewed information and agreed that Jayco would be required to file recall after Dexter filed for products built on the recalled Dexter Axles.

Description of Remedy :

Description of Remedy Program : Jayco Dealers will replace defective axles or service axle (hubs replaced) as required at NO charge to the customer
How Remedy Component Differs from Recalled Component : NR
Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : Jayco will contact current owner on record due to parts availability from Dexter and Instructions from Dexter
Planned Dealer Notification Date : NR - NR
Planned Owner Notification Date : NR - NR

* NR - Not Reported