

# Part 573 Safety Recall Report

# 18V-627

**Manufacturer Name :** Forest River, Inc.**Submission Date :** SEP 13, 2018**NHTSA Recall No. :** 18V-627**Manufacturer Recall No. :** 500-0855**Manufacturer Information :**

Manufacturer Name : Forest River, Inc.

Address : 55470 CR 1

P.O. Box 3030 Elkhart IN 46515-3030

Company phone : 1-800-348-7440

**Population :**

Number of potentially involved : 144

Estimated percentage with defect : NR

**Vehicle Information :**

Vehicle 1 : 2019-2019 Forest River Inc. East to West - DET25KRB, DET27K2D, DET27KNS, DET28KBS, DET28KRD, DET29K2S, DET29KRK, DET31K3S, DTT25KRB, DTT27K2D, DTT27KNS, DTT28KBS, DTT29K2S, DTT31K3S

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : The plant was using a Carbon Monoxide/LP (Propane) detector combination. Using purchasing records, the plant was able to determine a clerical error made in July of 2018 resulting in the plant installing a LP detector only.

On August 31st, 2018 the correct combination of Carbon Monoxide/LP (Propane) detector began being installed.

Production Dates : JUL 12, 2018 - AUG 31, 2018

VIN Range 1 : Begin :

NR

End : NR

 Not sequential**Description of Defect :**

Description of the Defect : Vehicles potentially were manufactured without the Carbon Monoxide Detector

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : A consumer may not be alerted to a Carbon Monoxide incident, potentially increasing the risk of injury.

Description of the Cause : A Carbon Monoxide detector was not installed during manufacturing of the vehicles.

Identification of Any Warning that can Occur : None

**Supplier Identification :****Component Manufacturer**

Name : NR

Address : NR

NR

Country : NR

**Chronology :**

On 9/5/2018 during a review of the East to West plant's manufacturing processes, the plant discovered a possible issue involving a missing Carbon Monoxide detector. Forest River's Office of Corporate Compliance ("OCC") initiated an investigation into this concern. The investigation revealed that the Carbon Monoxide/LP combination detector that was actually installed in certain vehicles is only labeled to detect LP (Propane), and not LP (Propane) and Carbon Monoxide detector due to a clerical error when ordering the part.

On 9/7/2018 Forest River's Corporate Committee decided to conduct a recall.

**Description of Remedy :**

Description of Remedy Program : A battery powered Carbon Monoxide detector will be installed free of charge. The Carbon Monoxide detector will need to be installed by a Forest River dealer.

What is the Forest River Customer Service Phone Number? (574)  
264-6664 Ext 50008

How Remedy Component Differs from Recalled Component : The component will be a Carbon Monoxide detector. The LP detector will be left in the vehicle.

Identify How/When Recall Condition was Corrected in Production : On 8/31/2018 the plant identified the missing Carbon Monoxide detector, and immediately started installing a Carbon Monoxide/LP (Propane) detector

**Recall Schedule :**

Description of Recall Schedule : Forest River has the utmost urgency in our recalls. Forest River will send suspected VIN numbers to our third party vendor that is licensed to pull data on the current owner of the vehicles (as needed) once a formal NHTSA I.D. is provided. Forest River intends on pushing the mailing out as soon as NHTSA provides any correction(s) and an Acknowledgement Letter.

Planned Dealer Notification Date : SEP 13, 2018 - OCT 23, 2018

Planned Owner Notification Date : SEP 13, 2018 - OCT 23, 2018

\* NR - Not Reported