

Part 573 Safety Recall Report

18V-690

Manufacturer Name : Airstream, Inc.

Submission Date : OCT 03, 2018

NHTSA Recall No. : 18V-690

Manufacturer Recall No. : NR



Manufacturer Information :

Manufacturer Name : Airstream, Inc.

Address : 419 West Pike Street
PO Box 629 Jackson Center OH
45334-0629

Company phone : 937-596-6111

Population :

Number of potentially involved : 103

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2018-2019 Airstream Atlas

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : DIESEL

Descriptive Information : -The 49 CFR Part 571.302 includes all Atlas RV manufactured to date.
-All units manufactured to date contain the same material.
-Airstream/Atlas/Model Year 2018 involves 41 units.
- Airstream/Atlas/Model Year 2019 involves 62 units.
-103 Airstream Atlas's are affected.

Production Dates : NOV 17, 2017 - OCT 03, 2018

VIN Range 1 : Begin : 1B9KUWH29KJ305345 **End :** 1B9KUWH28KJ306616 Not sequential

Description of Noncompliance :

Description of the Noncompliance : The material used for the accordion style screen door does not comply with 49 CFR Part 571.302.

FMVSS 1 : 302 - Flammability of interior materials

FMVSS 2 : NR

Description of the Safety Risk : The flammability of the screen door does not comply with FMVSS 302. In the event of a fire, the screen door could burn quicker than expected resulting in personal injury.

Description of the Cause : The incorrect screen material was sourced for the screen door.

Identification of Any Warning that can Occur : None

Supplier Identification :**Component Manufacturer**

Name : NR
Address : NR
NR
Country : NR

Chronology :

On 9/7/18 during a site visit by a non-related vendor it was mentioned that the screen material being used for the accordion style screen door may not adhere to FMVSS 302. 9/7/18 contacted vendor to verify code compliance. 9/19/18 Vendor responded that the material had not been tested. 9/20/18 Airstream Compliance was notified. 9/20/18 Sample of material was sent for testing. 9/26/18 Received the failed test results. 9/28/18 Airstream Safety Committee convened to discuss the initiation of a recall.

Description of Remedy :

Description of Remedy Program : NR
How Remedy Component Differs NR
from Recalled Component :
Identify How/When Recall Condition NR
was Corrected in Production :

Recall Schedule :

Description of Recall Schedule : Airstream will notify dealers and owners of the affected vehicles by letter.
Planned Dealer Notification Date : NOV 30, 2018 - NOV 30, 2018
Planned Owner Notification Date : NOV 30, 2018 - NOV 30, 2018

* NR - Not Reported