

# Part 573 Safety Recall Report

# 18V-733

**Manufacturer Name :** Forest River, Inc.

**Submission Date :** OCT 19, 2018

**NHTSA Recall No. :** 18V-733

**Manufacturer Recall No. :** 49-0891



## Manufacturer Information :

## Population :

Manufacturer Name : Forest River, Inc.

Number of potentially involved : 26

Address : 55470 CR 1

Estimated percentage with defect : 100 %

P.O. Box 3030 Elkhart IN 46515-3030

Company phone : 1-800-348-7440

## Vehicle Information :

Vehicle 1 : 2019-2019 Forest River Inc. Impression - MPF3000RLS-49

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Since inception of this new model Primetime Impression Fifth Wheel MPF3000RLS-49. This is the only model affected.

Production Dates : OCT 02, 2018 - OCT 10, 2018

VIN Range 1 : Begin :

NR

End : NR

Not sequential

## Description of Noncompliance :

Description of the Noncompliance : The vehicles do not comply with FMVSS 108 "Required Lamps and Reflective Devices". The vehicles' amber side marker lights are not located as far to the front as practicable on the vehicle, consistent with the standard.

FMVSS 1 : 108 - Lamps, reflective devices, and assoc. Equipment

FMVSS 2 : NR

Description of the Safety Risk : Vehicles that do not contain the required number of lamps and reflective devices in the appropriate locations may be more difficult for other drivers to see.

Description of the Cause : The manufacturing plant did not properly follow manufacturing practices.

Identification of Any Warning that can Occur : None

## Supplier Identification :

**Component Manufacturer**

Name : NR  
Address : NR  
NR  
Country : NR

**Chronology :**

On October 15th, 2018, Forest River's PDI Quality Group conducted a routine inspection of the manufacturing plant and observed a vehicle that was missing its amber side marker reflectors. On October 16th, 2018, Forest River's PDI team initiated an investigation.

On October 19th, 2018, Forest River's Corporate Committee decided to conduct a recall to address this issue.

**Description of Remedy :**

Description of Remedy Program : Forest River will provide all remedy parts to the dealer and customer, free of charge. A dealership must install the remedy kit.

What is the Forest River Customer Service Phone Number? (574)  
862-1025

How Remedy Component Differs from Recalled Component : Amber side marker lights will be installed as far forward as practicable on each side of the vehicle.

Identify How/When Recall Condition was Corrected in Production : On October 15th the condition was corrected by the manufacturing plant

**Recall Schedule :**

Description of Recall Schedule : Forest River has the utmost urgency in our recalls. Forest River will send suspected VIN numbers to our third party vendor that is licensed to pull data on the current owner of the vehicles (as needed) once a formal NHTSA I.D. is provided. Forest River intends on pushing the mailing out as soon as NHTSA provides any correction(s) and an Acknowledgement Letter.

Planned Dealer Notification Date : OCT 19, 2018 - NOV 28, 2018

Planned Owner Notification Date : OCT 19, 2018 - NOV 28, 2018

\* NR - Not Reported