OMB Control No.: 2127-0004

Part 573 Safety Recall Report

18V-752

Manufacturer Name: Forest River, Inc.
Submission Date: OCT 25, 2018
NHTSA Recall No.: 18V-752
Manufacturer Recall No.: 75-0867



Manufacturer Information:

Population:

Manufacturer Name: Forest River, Inc.

Number of potentially involved: 3,606

Address: 55470 CR 1

Estimated percentage with defect : $100\,\%$

P.O. Box 3030 Elkhart IN 46515-3030

Company phone: 1-800-348-7440

Vehicle Information:

Vehicle 1: 2018-2019 Forest River Inc. 2018-2019 CHEROKEE – ALPHA WOLF AND ARCTIC

WOLF

Vehicle Type: TRAILERS

Body Style : Power Train : NR

Descriptive Information: The scope of the recall begins with the first model year vehicle manufactured with

this specific awning at the production plant. 2018-2019 CHEROKEE – ALPHA WOLF

CKT23RD-L-75 - 43, CKT26DBH-L-75 - 714, CKT26RL-L-75 - 23, CKT27RK-L-75 -

506, CKT29DQ-L-75 - 44, CKT29QB-L-75 - 136

2019 CHEROKEE – ARCTIC WOLF

 $\label{eq:ckf245Rk4-75-10} CKF245Rk4-75-10, CKF255DRL4-75-W-12, CKF265DBH8-75-379, CKF265DBH8-75-W-34, CKF285DRL4-75-369, CKF285DRL4-75-W-29, CKF295QSL8-75-382, CKF295QSL8-75-W-17, CKF305ML6-75-384, CKF315TBH8-75-397, CKF315TBH8-75-W-18$

Production Dates: JUL 27, 2018 - SEP 21, 2018

Description of Defect:

Description of the Defect: The fasteners used to mount the awning arms to the sidewall of the

recreational vehicles are of insufficient length, and/or quantity, this could

potentially allow the awning arm to come loose from the sidewall.

FMVSS 1: NR

FMVSS 2: NR

Description of the Safety Risk: The awning arm could potentially come loose from the sidewall, resulting in

personal property damage or injury.

Description of the Cause: The incorrect fasteners, and/or incorrect quantity of fasteners were used

during installation of this awning

Identification of Any Warning None

that can Occur:

Supplier Identification:

Component Manufacturer

Name: NR

Address: NR

NR

Country: NR

Chronology:

On 9/10/2018 Forest River's Office of Corporate Compliance received a report from our manufacturing plant stating they had received notification of a possible or upcoming Technical Service Bulletin from Carefree of Colorado.

On 9/10/2018 Forest River's Office of Corporate Compliance started an investigation.

On 10/04/2018 Forest River's Office of Corporate Compliance initiated a call to Carefree of Colorado regarding a copy of the bulletin and any data that would support failures occurring in the field.

On 10/12/2018 Forest River's Corporate Recall Committee was notified and supplied a copy of the bulletin, the committee asked for additional information to determine level of safety risk.

On 10/17/2018 Forest River's Office of Corporate Compliance, initiated a conference call with Carefree of Colorado to gather additional information.

On 10/19/2018 Forest River's Corporate Recall Committee voted to elevate the bulletin to recall

Description of Remedy:

Description of Remedy Program: Forest River will provide all required parts, and labor free of charge. A

dealership must install the required parts.

What is the Forest River Customer Service Phone Number? (260)

499-2100

How Remedy Component Differs The Carefree Longitude Adjustable Pitch Arm Set (Black) Part # 87JVAP-

from Recalled Component: MP is specific to this model only

Identify How/When Recall Condition During the week of March 1st, 2018 all awning arms are installed with the was Corrected in Production : correct length, and quantity of fasteners

Recall Schedule:

Description of Recall Schedule: Forest River has the utmost urgency in our recalls. Forest River will send

suspected VIN numbers to our third party vendor that is licensed to pull data on the current owner of the vehicles (as needed) once a formal NHTSA I.D. is provided. Forest River intends on pushing the mailing out as soon as NHTSA provides any correction(s) and an Acknowledgement

Letter.

Planned Dealer Notification Date : OCT 25, 2018 - DEC 04, 2018 Planned Owner Notification Date : OCT 25, 2018 - DEC 04, 2018

^{*} NR - Not Reported