

# Part 573 Safety Recall Report

# 18V-851

**Manufacturer Name :** Jayco, Inc.**Submission Date :** DEC 06, 2018**NHTSA Recall No. :** 18V-851**Manufacturer Recall No. :** 9901422**Manufacturer Information :**

Manufacturer Name : Jayco, Inc.

Address : 903 South Main Street

PO Box 460 Middlebury IN 46540

Company phone : 800-283-8267

**Population :**

Number of potentially involved : 149

Estimated percentage with defect : 100 %

**Vehicle Information :**

Vehicle 1 : 2019-2019 Travel Trailer White Hawk, Jay Flight SLX, Jay Feather

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

**Descriptive Information :** Dexter provided list of 328 axle serial numbers delivered to Jayco that Dexter recalled - We are currently working to complete the scope matching the Dexter axle serial numbers to Jayco Production records of Jayco products that were built on the recalled axles. Will edit information on 573 to call out final total of travel trailers upon completion. EDIT 12-6-18 AFFECTED UNITS

2019 White Hawk K1410095-0098 K1430123-0146 K1440171-0194 Jay Flight SLX

- K14J0111-0130 K17W0268-0287 7W0339-0359, K17Y0423-0437

Jay Feather - K1J90269-0278 AND J90303-0308 K1JA0205-0224

Production Dates : SEP 12, 2018 - OCT 02, 2018

VIN Range 1 : Begin :

NR

End : NR

 Not sequential**Description of Defect :**

**Description of the Defect :** Insufficient amount of grease was applied to bearing during the manufacturing stage at Dexter Plant

FMVSS 1 : NR

FMVSS 2 : NR

**Description of the Safety Risk :** May result in premature bearing failure, which can lead to separation of the hub from the axle, creating risk of a crash with personal injury and /or property damage.

**Description of the Cause :** NR

**Identification of Any Warning that can Occur :** NR

**Supplier Identification :****Component Manufacturer**

Name : Dexter Axle  
Address : NR  
Elkhart INDIANA 46515  
Country : United States

**Chronology :**

11-19-18 Jayco received official recall notification with PO information from Dexter Axle regarding specific D35 axles manufactured on September 10, 2018. Investigation started immediately to locate units produced with the recall axles. We are still finalizing the scope of affected units. 11-27-18 - Information presented to Safety Steering Committee who agreed a Recall for safety is required.

**Description of Remedy :**

Description of Remedy Program : Jayco Dealers will inspect the axle bearings and replace or repack per Dexter instructions at no charge.

How Remedy Component Differs from Recalled Component : Part number of the recalled axles: 0281869, 0320861, 0319499 manufactured at Dexter Plant September 10, 2018.

Identify How/When Recall Condition was Corrected in Production : NR

**Recall Schedule :**

Description of Recall Schedule : Upon receipt of recall number, and completion of affect scope of products, Jayco is prepared to release recall

Planned Dealer Notification Date : DEC 21, 2018 - DEC 21, 2018

Planned Owner Notification Date : DEC 21, 2018 - DEC 21, 2018

\* NR - Not Reported