

Part 573 Safety Recall Report

19V-024

Manufacturer Name : Airstream, Inc.

Submission Date : JAN 03, 2019

NHTSA Recall No. : 19V-024

Manufacturer Recall No. : NR



Manufacturer Information :

Manufacturer Name : Airstream, Inc.

Address : 419 West Pike Street
PO Box 629 Jackson Center OH
45334-0629

Company phone : 937-596-6111

Population :

Number of potentially involved : 189

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2019-2019 Airstream Basecamp X

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : - The recall population was determined by a review of vehicle records of the labels that were printed. - The information on the labels did not match the tires on the trailers. - The affected product is the Airstream/Basecamp X/Model Year 2019, available in the United States and Canada.

Production Dates : JUN 22, 2018 - NOV 26, 2018

VIN Range 1 : Begin : 1SMG4DC14KJ204194 **End :** 1SMG4DC12KJ204453 Not sequential

Description of Noncompliance :

Description of the Noncompliance : The tire information printed on the Federal Certification label and Tire Placard are incorrect. The information printed was for 235/55R18 Load Range D tires with 80 psi, when it should have been for 235/75R15 Load Range D tires with 51 psi.

FMVSS 1 : 110 - Tire selection and rims

FMVSS 2 : 567 - Certification

Description of the Safety Risk : Per the information contained on the labels, an owner could overinflate their tires installed on the trailer.

Description of the Cause : The tire information for the Basecamp X differs from the Basecamp because the tire size being installed on the Basecamp X is a larger "off-road" style tire.

Identification of Any Warning that can Occur : None

Supplier Identification :**Component Manufacturer**

Name : NR
Address : NR
NR
Country : NR

Chronology :

November 26, 2018 - Quality Control inspection discovered incorrect labels were being printed and placed on certain trailers. November 27, 2018 - The Basecamp model was identified as having incorrect labels. November 29, 2018 - Investigation was started of labeling for prior 10 model years across all vehicles produced by Airstream. December 5, 2018 - Basecamp X Model was corrected in production and all units on premises were corrected. January 2, 2019 - Investigation into prior model year labeling was concluded. January 3, 2019 - 573 submitted to NHTSA for affected Basecamp X model.

Description of Remedy :

Description of Remedy Program : Corrected labels will be sent to affected customers and dealers for installation. This will be done at no cost to the owner.

How Remedy Component Differs from Recalled Component : The tire information has been corrected from 235/55R15 with 80 psi to 235/75R15 with 51 psi.

Identify How/When Recall Condition was Corrected in Production : The issue was corrected on December 5th, 2018.

Recall Schedule :

Description of Recall Schedule : Airstream will send dealer and owner notification letters once approved by NHTSA.
Planned Dealer Notification Date : NR - NR
Planned Owner Notification Date : NR - NR

* NR - Not Reported