

# Part 573 Safety Recall Report

# 19V-050

**Manufacturer Name :** Forest River, Inc.

**Submission Date :** JAN 23, 2019

**NHTSA Recall No. :** 19V-050

**Manufacturer Recall No. :** 45-0931



## Manufacturer Information :

Manufacturer Name : Forest River, Inc.

Address : 55470 CR 1

P.O. Box 3030 Elkhart IN 46515-3030

Company phone : 1-800-348-7440

## Population :

Number of potentially involved : 7

Estimated percentage with defect : 100 %

## Vehicle Information :

Vehicle 1 : 2018-2018 Forest River Inc. XLR - XLT26HFS, XLT26HFS-W, XLT27KW

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : A change is the manufacturing personnel allowed the affected models to be manufactured without an LP/CO detector

XLT26HFS - 2

XLT26HFS-W - 1

XLT27KW - 4

Production Dates : FEB 20, 2018 - NOV 21, 2018

VIN Range 1 : Begin :

NR

End : NR

Not sequential

## Description of Defect :

Description of the Defect : Vehicles potentially were manufactured without the LP (Propane) & Carbon Monoxide Detector

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : A consumer may not be alerted to a Carbon Monoxide incident, potentially increasing the risk of injury.

Description of the Cause : Inconsistent installation practice in the manufacturing plant due to a change in manufacturing personnel

Identification of Any Warning that can Occur : None

**Supplier Identification :****Component Manufacturer**

Name : NR  
Address : NR  
NR  
Country : NR

**Chronology :**

On January 16th, 2019 Forest River's Manufacturing plant was alerted by a dealer that the LP/CO detector was not installed in a specific unit. On that same day a scope of VINs were pulled around the time of production that was determined by production records to reflect the change in personnel. All units were inspected, and 6 were found to be missing.

On January 18th, 2019 Forest Rivers Corporate Recall Committee voted to recall.

**Description of Remedy :**

Description of Remedy Program : Forest River will provide the LP/CO detector and labor free of charge, a dealership will need to perform this recall.

What is the Forest River Customer Service Phone Number? (574)  
642-0432

How Remedy Component Differs from Recalled Component : All units will have a LP/CO detector installed.

Identify How/When Recall Condition was Corrected in Production : The issue was remedied in manufacturing by retraining employees to follow consistent manufacturing methods. This training took place in early March 2018.

**Recall Schedule :**

Description of Recall Schedule : Forest River has the utmost urgency in our recalls. Forest River will send suspected VIN numbers to our third party vendor that is licensed to pull data on the current owner of the vehicles (as needed) once a formal NHTSA I.D. is provided. Forest River intends on pushing the mailing out as soon as NHTSA provides any correction(s) and an Acknowledgement Letter.

Planned Dealer Notification Date : MAR 11, 2019 - MAR 22, 2019

Planned Owner Notification Date : MAR 11, 2019 - MAR 22, 2019

\* NR - Not Reported