

Part 573 Safety Recall Report

19V-173

Manufacturer Name : Jayco, Inc.**Submission Date :** MAR 05, 2019**NHTSA Recall No. :** 19V-173**Manufacturer Recall No. :** 9901428**Manufacturer Information :**

Manufacturer Name : Jayco, Inc.

Address : 903 South Main Street

PO Box 460 Middlebury IN 46540

Company phone : 800-283-8267

Population :

Number of potentially involved : 1,660

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2019-2019 Jayco Fifth Wheel North Point Pinnacle

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Production records of all products with Carefree Altitude Series Awning/s
 2019 NorthPoint K1LC0051-0150 LD0051-0128 LE0050-0146 LL0051-0437
 LP0051-0109 LR0051-0140 LW0051-0094 LY0051-0110 LZ0050-0110

2019 Pinnacle K1RG0050-0182 RL0051-0278 RM0051-0131 RP0051-0108
 RR0051-0122 RT0051-0081 RU0050-0191 RV0052-0110

Production Dates : MAR 09, 2018 - JAN 24, 2019

VIN Range 1 : Begin :

NR

End : NR

 Not sequential**Description of Defect :**

Description of the Defect : Circuit for accessory awning is not protected per RVIA code for low voltage system requirements Circuit for the Awning accessory has a 15amp fuse when a 5amp fuse is required.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : A short in circuit could result in thermal event.

Description of the Cause : Incorrect specification for 18 gauge wire

Identification of Any Warning NR
 that can Occur :

Supplier Identification :**Component Manufacturer**

Name : NR
Address : NR
NR
Country : NR

Chronology :

1-2019 Dealer submitted inspection results of a 2019 Pinnacle that had a thermal event while still in the Dealer's possession. - the Insurance inspection noted that the awning wiring had been pinched by moving parts of the awning. Upon further investigation by Jayco Corp Engineering, was discovered that the circuit or the Awning had a 15 amp fuse, when a 5amp fuse is required. - 1-24-19 - Engineering made a immediate change to wiring specification for the awning in production. 2-2019 Engineering continued their research with creating repair for various models of affected fifth wheels - different locaton of awnings on affected units with mulitple access routes to wiring - 2-28-19 Safety Committee Reviewed all details of Incident and agreed that safesty recall is required.

Description of Remedy :

Description of Remedy Program : Install 5amp fuse and fuse holder to each Awning Accessory circuit - some units have 2 awnings while others only 1

How Remedy Component Differs from Recalled Component : 5 amp fuse installed

Identify How/When Recall Condition was Corrected in Production : Corrected 1-24-19 immediatley upon knowledge of the error

Recall Schedule :

Description of Recall Schedule : Jayco is ready to release recall upon receipt of REcall number from NHTSA

Planned Dealer Notification Date : MAR 20, 2019 - MAR 20, 2019

Planned Owner Notification Date : MAR 20, 2019 - MAR 20, 2019

* NR - Not Reported