

# Part 573 Safety Recall Report

# 18V-387

**Manufacturer Name :** Newmar Corporation**Submission Date :** JUN 08, 2018**NHTSA Recall No. :** 18V-387**Manufacturer Recall No. :** NR**Manufacturer Information :****Population :**

Manufacturer Name : Newmar Corporation

Number of potentially involved : 77

Address : 355 North Delaware Street  
PO Box 30 Nappanee IN 46550

Estimated percentage with defect : 100 %

Company phone : 574-773-7791

**Vehicle Information :**

Vehicle 1 : 2018-2019 Newmar Mountain Aire

Vehicle Type : BUSES, MEDIUM &amp; HEAVY VEHICLES

Body Style :

Power Train : NR

**Descriptive Information :** On certain motorhomes, the windshield wiper arms may not have the correct bend. Not having the correct bend on the windshield wiper arm may reduce the driver's visibility. Reduced visibility increases the risk of a crash and/or property damage.  
Correction: Dealers will replace the wiper arms free of charge.

Production Dates : JAN 29, 2018 - MAY 31, 2018

VIN Range 1 : Begin : NR End : NR

 Not sequential

Vehicle 2 : 2018-2019 Newmar London Aire

Vehicle Type : BUSES, MEDIUM &amp; HEAVY VEHICLES

Body Style :

Power Train : NR

**Descriptive Information :** On certain motorhomes, the windshield wiper arms may not have the correct bend. Not having the correct bend on the windshield wiper arm may reduce the driver's visibility. Reduced visibility increases the risk of a crash and/or property damage.  
Correction: Dealers will replace the wiper arms free of charge.

Production Dates : JAN 29, 2018 - MAY 31, 2018

VIN Range 1 : Begin : NR End : NR

 Not sequential

Vehicle 3 : 2018-2019 Newmar Essex

Vehicle Type : BUSES, MEDIUM &amp; HEAVY VEHICLES

Body Style :

Power Train : NR

**Descriptive Information :** On certain motorhomes, the windshield wiper arms may not have the correct bend. Not having the correct bend on the windshield wiper arm may reduce the driver's visibility. Reduced visibility increases the risk of a crash and/or property damage.

Correction: Dealers will replace the wiper arms free of charge.

Production Dates : JAN 29, 2018 - MAY 31, 2018

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 4 : 2018-2019 Newmar King Aire

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** On certain motorhomes, the windshield wiper arms may not have the correct bend. Not having the correct bend on the windshield wiper arm may reduce the driver's visibility. Reduced visibility increases the risk of a crash and/or property damage.  
Correction: Dealers will replace the wiper arms free of charge.

Production Dates : JAN 29, 2018 - MAY 31, 2018

VIN Range 1 : Begin :

NR

End : NR

Not sequential

## Description of Defect :

**Description of the Defect :** On certain motorhomes, the windshield wiper arms may not have the correct bend. Not having the correct bend on the windshield wiper arm may reduce the driver's visibility. Reduced visibility increases the risk of a crash and/or property damage.

FMVSS 1 : 104 - Windshield wiping and washing systems

FMVSS 2 : NR

**Description of the Safety Risk :** Not having the correct bend on the windshield wiper arm may reduce the driver's visibility. Reduced visibility increases the risk of a crash and/or property damage.

**Description of the Cause :** the windshield wiper arms may not have the correct bend to make contact with the windshield.

**Identification of Any Warning that can Occur :** NR

## Supplier Identification :

### Component Manufacturer

Name : Newmar Corporation

Address : 355 N Delaware St.  
Nappanee INDIANA 46550

Country : United States

**Chronology :**

On 6/1/2018 Newmar was made aware of a possible wiper arm issue. On 6/8/2018, Newmar is giving notice of defect.

**Description of Remedy :**

Description of Remedy Program : Dealers will replace the wiper arms free of charge.

How Remedy Component Differs from Recalled Component : Wiper arm will have the correct bend.

Identify How/When Recall Condition was Corrected in Production : New replacement wiper arms will be installed.

**Recall Schedule :**

Description of Recall Schedule : NR

Planned Dealer Notification Date : AUG 08, 2018 - AUG 08, 2018

Planned Owner Notification Date : AUG 08, 2018 - AUG 08, 2018

\* NR - Not Reported