

Part 573 Safety Recall Report

18V-479

Manufacturer Name : Daimler Trucks North America LLC**Submission Date :** JUL 18, 2018**NHTSA Recall No. :** 18V-479**Manufacturer Recall No. :** FL-779**Manufacturer Information :**

Manufacturer Name : Daimler Trucks North America LLC

Address : 4747 N. Channel Avenue

Portland OR 97217-3849

Company phone : 800-745-8000

Population :

Number of potentially involved : 425

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2019-2019 Freightliner Cascadia

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : Vehicles equipped with certain Conti Hybrid HS3 Tires

Production Dates : MAR 23, 2018 - APR 28, 2018

VIN Range 1 : Begin :

NR

End : NR

 Not sequential**Description of Defect :**

Description of the Defect : Continental Tire The Americas, LLC. States per Recall 18T-006 "The Conti Hybrid HS3 11R22.5 Load Range G tires may have "Visible Cords through the innerliner"

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Continental Tire the Americas, LLC. States per Recall 18T-006 "Affected tires may experience a sudden air loss, which could result in a loss of control potentially leading to a risk of serious injury or death."

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :

Component Manufacturer

Name : Continental Tire the Americas, LLC.
Address : 1830 Macmillan Park Drive
Fort Mill SOUTH CAROLINA 29707
Country : United States

Chronology :

noncompliance decision.:

In June 2018, DTNA was notified of recall 18T-006 related to certain Continental "Conti Hybrid HS3" Tires. DTNA began an investigation to determine the scope of the issue. On July 12th 2018, DTNA decided to initiate a voluntary safety recall for vehicles equipped with the potentially defective Continental tire.

Description of Remedy :

Description of Remedy Program : Affected tires will be inspected and replaced where required. Repairs will be performed by Continental Tire The Americas, LLC. authorized service facilities. Copies of reimbursement plans will be submitted as a supplemental report when available.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : DTNA will notify affected customers. Customer notification will be made by first class mail using Daimler Trucks North America records to determine the customers affected.

Planned Dealer Notification Date : SEP 15, 2018 - SEP 15, 2018

Planned Owner Notification Date : SEP 15, 2018 - SEP 15, 2018

* NR - Not Reported