

Part 573 Safety Recall Report

18V-920

Manufacturer Name : Custom Truck And Body Works**Submission Date :** DEC 20, 2018**NHTSA Recall No. :** 18V-920**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Custom Truck And Body Works

Address : 13787 Whitehouse Parkway

Woodbury GA 30293

Company phone : 7065539178

Population :

Number of potentially involved : NR

Estimated percentage with defect : NR

Vehicle Information :

Vehicle 1 : 2017-2019 Type 1, 2 & 3 Ambulances

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : This recalls population was determined by assistance from Whelen Engineering who provided us with a list of purchase order numbers that were filled with affected lights. Products affected by the recall may illuminate when the vehicle's brake pedal has not been pressed. While we are currently unaware of the total number estimated by Whelen Engineering to be defective, we believe our number of affected parts to be 76, as 2 of these lights are on each of the 38 trucks we have listed.

Production Dates : NOV 01, 2017 - MAY 16, 2018

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Vehicle 2 : 2017-2019 Rescue Trucks

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : This recalls population was determined by assistance from Whelen Engineering who provided us with a list of purchase order numbers that were filled with affected lights. Products affected by the recall may illuminate when the vehicle's brake pedal has not been pressed. While we are currently unaware of the total number estimated by Whelen Engineering to be defective, we believe our number of affected parts to be 76, as 2 of these lights are on each of the 38 trucks we have listed.

Production Dates : NOV 01, 2017 - MAY 16, 2018

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Vehicle 3 : 2017-2019 Pumper & Tanker Trucks

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : This recalls population was determined by assistance from Whelen Engineering who provided us with a list of purchase order numbers that were filled with affected lights. Products affected by the recall may illuminate when the vehicle's brake pedal has not been pressed. While we are currently unaware of the total number estimated by Whelen Engineering to be defective, we believe our number of affected parts to be 76, as 2 of these lights are on each of the 38 trucks we have listed.

Production Dates : NOV 01, 2017 - MAY 16, 2018

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Description of Defect :

Description of the Defect : Whelen's 60BTT 600 Series LED Brake Lights may illuminate when the vehicle's brake pedal has not been pressed.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : This could cause other drivers to become confused and make an necessary change in their driving, like applying their brakes or snatching the steering wheel, increasing the chances of an accident occurring.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :

Component Manufacturer

Name : Whelen Engineering

Address : 51 Winthrop Road
Chester CONNECTICUT 06412

Country : United States

Chronology :

NR

Description of Remedy :

Description of Remedy Program : NR

How Remedy Component Differs NR
from Recalled Component :

Identify How/When Recall Condition NR
was Corrected in Production :

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported