

Part 573 Safety Recall Report

18V-462

Manufacturer Name : KZRV, L.P.**Submission Date :** JUL 11, 2018**NHTSA Recall No. :** 18V-462**Manufacturer Recall No. :** KZ-2018-005**Manufacturer Information :**

Manufacturer Name : KZRV, L.P.

Address : 0985 N 900W

Shipshewana IN 46565

Company phone : 800-768-4016x154/153

Population :

Number of potentially involved : 500

Estimated percentage with defect : NR

Vehicle Information :

Vehicle 1 : 2018-2019 KZ RV Sportsmen

Vehicle Type : TRAILERS

Body Style : OTHER

Power Train : NR

Descriptive Information : The safety defect was determined through warranty claims that indicated heat damage to outside kitchen counter tops due to gas leaks occurring during pre-delivery inspections at dealers.

Production Dates : JUL 01, 2017 - JUN 26, 2018

VIN Range 1 : Begin :

NR

End : NR

 Not sequential**Description of Defect :**

Description of the Defect : The propane system testing was not properly done during the manufacturing process. Vehicles not properly tested could have a propane gas leak at the back of the outside kitchen cooktop.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Vehicles not properly tested could have a propane gas leak at the back of the outside kitchen cooktop. If a gas leak occurred a fire or explosion could occur which could result in personal injury.

Description of the Cause : Production not properly educated on the testing process.

Identification of Any Warning None
that can Occur :

Supplier Identification :

Component Manufacturer

Name : NR
Address : NR
NR
Country : NR

Chronology :

NR

Description of Remedy :

Description of Remedy Program : TBD
How Remedy Component Differs from Recalled Component : TBD
Identify How/When Recall Condition was Corrected in Production : TBD

Recall Schedule :

Description of Recall Schedule : NR
Planned Dealer Notification Date : NR - NR
Planned Owner Notification Date : NR - NR

* NR - Not Reported