

Part 573 Safety Recall Report

18V-526

Manufacturer Name : KZRV, L.P.**Submission Date :** AUG 10, 2018**NHTSA Recall No. :** 18V-526**Manufacturer Recall No. :** KZ-2018-006**Manufacturer Information :**

Manufacturer Name : KZRV, L.P.

Address : 0985 N 900W

Shipshewana IN 46565

Company phone : 800-768-4016x154/153

Population :

Number of potentially involved : 61

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2018-2019 KZ RV Sportsmen 333BHK

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The vehicles subject to this recall were built with the propane distribution system routed in an unprotected wheel well.

Production Dates : OCT 31, 2017 - JUL 10, 2018

VIN Range 1 : Begin :

NR

End : NR

 Not sequential**Description of Defect :**

Description of the Defect : The liquid propane supply line is routed through a wheel well and is not adequately protected from debris.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : The liquid propane supply system may be damaged by debris and could result in a fire or explosion resulting in personal injury or death.

Description of the Cause : Production error.

Identification of Any Warning that can Occur : None

Supplier Identification :**Component Manufacturer**

Name : NR

Address : NR
NR
Country : NR

Chronology :

7-20-2018 QC recognized an issue with gas line placement of LP Lines 7-20-2018 Production units are correct and yard inventory inspected and corrected as necessary 7-27-2018 A safety committee meeting is held and research regarding prior production and cause is reviewed. Inquiries are forwarded to determine if units exist in the field. 8-6-2018 A safety committee meeting is held and reviews data on units in the field . The determination is made to issue a recall.

Description of Remedy :

Description of Remedy Program : Shielding of the gas lines by utilizing a steel plate to provide protection.

How Remedy Component Differs NR
from Recalled Component :

Identify How/When Recall Condition was Corrected in Production : The gas lines were re-routed in production to avoid being exposed in a wheel well.

Recall Schedule :

Description of Recall Schedule : KZ will notify the dealers and owners of these recreational vehicles by letter. A final copy of the owner letter will be provided to NHTSA, along with dealer repair instructions.

Planned Dealer Notification Date : OCT 06, 2018 - OCT 06, 2018

Planned Owner Notification Date : OCT 06, 2018 - OCT 06, 2018

* NR - Not Reported