

Part 573 Safety Recall Report

18V-540

Manufacturer Name : KZRV, L.P.**Submission Date :** AUG 16, 2018**NHTSA Recall No. :** 18V-540**Manufacturer Recall No. :** KZ-2018-08**Manufacturer Information :**

Manufacturer Name : KZRV, L.P.

Address : 0985 N 900W

Shipshewana IN 46565

Company phone : 800-768-4016x154/153

Population :

Number of potentially involved : 1,160

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2017-2019 KZ RV Durango, Venom & Sidewinder models

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The Federal Certification Label indicates an incorrect tire size. As such, these vehicles fail to comply with the requirements of 49 CFR Part 567, "Certification" and can create a safety risk.

Production Dates : JAN 11, 2017 - AUG 09, 2018

VIN Range 1 : Begin : 4EZFV3829H6012559 End : 4EZFV3625K6086961 Not sequential**Description of Defect :**

Description of the Defect : The Federal Certification label has incorrect tire information listed. The attached tag states a tire size of ST235/80R16G. The installed tires are ST235/85R16G.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : The consumer is misinformed and could potentially install the wrong sized tires which reduces their load carrying capacity.

Description of the Cause : Data entry error into the computer systems.

Identification of Any Warning that can Occur : None

Supplier Identification :

Component Manufacturer

Name : NR
Address : NR
NR
Country : NR

Chronology :

8-10-2018 - Engineering is informed of an incorrect labeling. Further inspection reveals additional errors.
8-10-2018 - A safety committee meeting is held and the determination is made to issue a recall.

Description of Remedy :

Description of Remedy Program : Replace the existing label with a new label that has the correct tire size information listed of ST235/85R16G.
How Remedy Component Differs from Recalled Component : NR
Identify How/When Recall Condition was Corrected in Production : The tire information was corrected in the computer systems and the labels are now printing with the correct information.

Recall Schedule :

Description of Recall Schedule : KZ will notify the dealers and owners of these recreational vehicles by letter. A final copy of the owner letter will be provided to NHTSA, along with dealer repair instructions.
Planned Dealer Notification Date : OCT 08, 2018 - OCT 08, 2018
Planned Owner Notification Date : OCT 08, 2018 - OCT 08, 2018

* NR - Not Reported