

Part 573 Safety Recall Report

18V-603

Manufacturer Name : Turtle Top

Submission Date : SEP 10, 2018

NHTSA Recall No. : 18V-603

Manufacturer Recall No. : NR



Manufacturer Information :

Manufacturer Name : Turtle Top

Address : 67819 State Road 15

New Paris IN 46553

Company phone : 574-831-4340

Population :

Number of potentially involved : 180

Estimated percentage with defect : NR

Vehicle Information :

Vehicle 1 : 2013-2018 Turtle Top Odyssey, Van Terra, Terra Transit

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : ALL

Power Train : NR

Descriptive Information : If the position input cam fails and the lift operator continues to press the “up” button on the operating pendant while the lift is occupied, the cutoff switch is dis-abled and the platform can travel past the vehicle floor height, potentially causing the occupant to tip inwards, toward the vehicle.

Production Dates : JAN 02, 2013 - AUG 31, 2018

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Description of Defect :

Description of the Defect : If the position input cam fails and the lift operator continues to press the “up” button on the operating pendant while the lift is occupied, the cutoff switch is dis-abled and the platform can travel past the vehicle floor height, potentially causing the occupant to tip inwards, toward the vehicle.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : If the position input cam fails and the lift operator continues to press the “up” button on the operating pendant while the lift is occupied, the cutoff switch is dis-abled and the platform can travel past the vehicle floor height, potentially causing the occupant to tip inwards, toward the vehicle.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : Ricon

Address : 1135 Aviation Place
San Fernando CALIFORNIA 91340

Country : United States

Chronology :

NR

Description of Remedy :

Description of Remedy Program : NR

How Remedy Component Differs NR
from Recalled Component :Identify How/When Recall Condition NR
was Corrected in Production :**Recall Schedule :**

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported