

# Part 573 Safety Recall Report

# 18V-689

**Manufacturer Name :** Jayco, Inc.**Submission Date :** OCT 02, 2018**NHTSA Recall No. :** 18V-689**Manufacturer Recall No. :** na**Manufacturer Information :**

Manufacturer Name : Jayco, Inc.

Address : 903 South Main Street

PO Box 460 Middlebury IN 46540

Company phone : 800-283-8267

**Population :**

Number of potentially involved : 24

Estimated percentage with defect : 100 %

**Vehicle Information :**

Vehicle 1 : 2019-2019 Class C Motor Home Precept, Precept Prestige

Vehicle Type : BUSES, MEDIUM &amp; HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : Ford submitted list of 24 affected Chassis VINS delivered to Jayco - affected VINS were matched to Jayco product serial numbers

2019 Precept

K1UA0085

K1UG0054, 0055, 0058

K1UK0101-0109

K1UL0166-0174

Production Dates : JUL 17, 2018 - OCT 10, 2018

VIN Range 1 : Begin :

NR

End : NR

 Not sequential**Description of Defect :**

Description of the Defect : Per Ford Recall 18V470 - chassis front wheel hub assemblies may contain wheel studs that were not heat treated properly.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Per Ford Recall 18V470 - if a sufficient quantity of wheel studs break on one hub assembly, vehicle handling could be affected, increasing the risk of a crash

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

**Supplier Identification :****Component Manufacturer**

Name : Ford Motor Company  
Address : NR  
NR  
Country : United States

**Chronology :**

8-29-18 List of 24 Ford chassis affected by FORD recall 18V470 submitted to match to current Jayco motorized product.  
9-27-18 Jayco Safety Committee reviewed details of Ford Recall 18V470 and decided that pass through recall was required.

**Description of Remedy :**

Description of Remedy Program : Ford Service Centers will inspect the front wheel hub assemblies and studs and replace affected studs when necessary free of charge. .  
How Remedy Component Differs from Recalled Component : NR  
Identify How/When Recall Condition was Corrected in Production : Spartan came on site and performed recall remedy on affected chassis

**Recall Schedule :**

Description of Recall Schedule : Jayco will not release Recall notification for this recall - FORD is administering the recall and has released to current owner on record.  
Planned Dealer Notification Date : NR - NR  
Planned Owner Notification Date : NR - NR

\* NR - Not Reported