OMB Control No.: 2127-0004

# Part 573 Safety Recall Report

18V-718

**Manufacturer Name:** Riverside Travel Trailer, Inc.

**Submission Date:** OCT 12, 2018 **NHTSA Recall No.:** 18V-718

Manufacturer Recall No.: NR



#### **Manufacturer Information:**

Manufacturer Name: Riverside Travel Trailer, Inc.

Address: P.O. Box 1099

Peru IN 46970

Company phone: 765-472-3920

## **Population:**

Number of potentially involved: 1 Estimated percentage with defect: 100 %

#### **Vehicle Information:**

Vehicle 1: 2018-2018 Riverside Dream

Vehicle Type: TRAILERS

Body Style : ALL Power Train : NR

Descriptive Information: One model with NHTSA Recall# 18E-050 Solera Smart Arm Awning.

Production Dates: AUG 15, 2017 - AUG 15, 2017

VIN Range 1: Begin: 521BT2113JP016837 End: 521BT2113JP016837 ☐ Not sequential

### **Description of Defect:**

Description of the Defect: NHTSA equipment recall #18E-050

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: Deployment of awning while the vehicle is in motion could cause loss of

vehicle control and a crash, resulting in personal property damage or injury

Description of the Cause: Water intrusion into the Smart Arm awning control module wiring harness

could cause a short circuit and inadvertently activate Smart Arm awning

deployment.

Identification of Any Warning NR

that can Occur:

## **Supplier Identification:**

#### **Component Manufacturer**

Name: Lippert Components, Inc.

Address: PO Box 2888

Elkhart INDIANA 46515

**Country: United States** 

# **Chronology:**

Please see NHTSA Recall # 18E-050

## **Description of Remedy:**

Description of Remedy Program: Please see NHTSA Recall #18E-050

How Remedy Component Differs Please see NHTSA Recall #18E-050

from Recalled Component:

Identify How/When Recall Condition Please see NHTSA Recall #18E-050

was Corrected in Production:

#### Recall Schedule:

Description of Recall Schedule: Riverside Travel Trailer, Inc. will notify the dealer and the end user of

this product by mail, informing them that LCI will reimburse the end user

for repair or replacement of the affected parts.

Planned Dealer Notification Date: OCT 15, 2018 - OCT 15, 2018

Planned Owner Notification Date: NR - NR

\* NR - Not Reported