

Part 573 Safety Recall Report

19V-080

Manufacturer Name : Lakota Corporation

Submission Date : FEB 11, 2019

NHTSA Recall No. : 19V-080

Manufacturer Recall No. : NR



Manufacturer Information :

Manufacturer Name : Lakota Corporation

Address : PO Box 219

4 Stoutco Drive Bristol IN 46507

Company phone : 574-848-1636

Population :

Number of potentially involved : 300

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2018-2019 Lakota Bighorn, Charger, Colt, Livestock Edition,

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : We changed vendors for our tires/wheels and created our tire data sheet off of a spread sheet they provided to us. We were not aware one of the tire/wheel sets we ordered were different from the ones on the spreadsheet and consequently we have incorrectly identified the weight capacity on tires.

Production Dates : JUN 16, 2017 - FEB 08, 2019

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Description of Noncompliance :

Description of the Noncompliance : incorrect tire data listed on federal placard, FMVSS 574 or 49 CFR Part 567 certification

FMVSS 1 : 574 - Tire Identification & Recordkeeping

FMVSS 2 : NR

Description of the Safety Risk : possible overload of tires which can lead to tire failure and risk of accident

Description of the Cause : failure to do proper data research and records incorrect

Identification of Any Warning that can Occur : NR

Supplier Identification :

Component Manufacturer

Name : NR
Address : NR
NR
Country : NR

Chronology :

we are looking at changing a particular tire/wheel combination we offer and an engineer was looking at the current product and realized what we have documented does not match the weights

Description of Remedy :

Description of Remedy Program : we will release a recall to dealers and retail owners
we will provide new placards with the correct data listed at no charge
we will pay dealers/service centers to install the new placards

How Remedy Component Differs from Recalled Component : proper weight capacity data listed

Identify How/When Recall Condition was Corrected in Production : the proper weight capacity was documented and all placards will have the proper weight capacity listed as of 2/8/2019

Recall Schedule :

Description of Recall Schedule : NR
Planned Dealer Notification Date : MAR 11, 2019 - MAR 12, 2019
Planned Owner Notification Date : MAR 18, 2019 - MAR 25, 2019

* NR - Not Reported