

# Part 573 Safety Recall Report

# 19V-165

**Manufacturer Name :** KZRV, L.P.**Submission Date :** MAR 04, 2019**NHTSA Recall No. :** 19V-165**Manufacturer Recall No. :** KZ-2019-01**Manufacturer Information :**

Manufacturer Name : KZRV, L.P.

Address : 0985 N 900W

Shipshewana IN 46565

Company phone : 800-768-4016x154/153

**Population :**

Number of potentially involved : 1,164

Estimated percentage with defect : 80 %

**Vehicle Information :**

Vehicle 1 : 2019-2019 KZ RV Sonic Lite

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : These units were produced with the Capital cooktop as the original equipment.

Production Dates : AUG 06, 2018 - FEB 12, 2019

VIN Range 1 : Begin : NR End : NR  Not sequential

Vehicle 2 : 2019-2019 KZ RV Sportsmen Classic

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : These units were produced with the Capital cooktop as the original equipment.

Production Dates : AUG 06, 2018 - FEB 12, 2019

VIN Range 1 : Begin : NR End : NR  Not sequential

Vehicle 3 : 2019-2019 KZ RV Escape

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : These units were produced with the Capital cooktop as the original equipment.

Production Dates : AUG 06, 2018 - FEB 12, 2019

VIN Range 1 : Begin : NR End : NR  Not sequential

**Description of Defect :**

Description of the Defect : The Capital cooktop does not perform safely in this application.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : When the furnace is running, the cooktop's flame can become inverted. Excessive heat buildup then occurs which poses a burn hazard.

Description of the Cause : In the current installation the cooktop becomes very sensitive to air drafts.

Identification of Any Warning NR  
that can Occur :

**Supplier Identification :****Component Manufacturer**

Name : NR

Address : NR

NR

Country : NR

**Chronology :**

NR

**Description of Remedy :**

Description of Remedy Program : NR

How Remedy Component Differs NR  
from Recalled Component :

Identify How/When Recall Condition NR  
was Corrected in Production :

**Recall Schedule :**

Description of Recall Schedule : KZ will notify the dealers and owners of these recreational vehicles by letter. A final copy of the owner letter and dealer repair instructions will be provided to NHTSA.

Planned Dealer Notification Date : MAY 03, 2019 - MAY 03, 2019

Planned Owner Notification Date : MAY 03, 2019 - MAY 03, 2019

\* NR - Not Reported